

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0381/2021/CCS
DATE : 4-May-21
WIP : 25801

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 4/5/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : POON KOK WAH
ADDRESS : 56A LORONG H TELOK KURAU
SINGAPORE 426064
TELEPHONE : HP +65 96751078
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070036973
VEHICLE NO : **SMN 3284 A**
MODEL CODE : AUDI A3 SPORTBACK 1.0 TFSI
MODEL YEAR : 31/7/2019
ENGINE NO : CHZ B23435
CHASSIS NO : WAUZZZ8V6KA079444
MILEAGE : -
DATE IN : 3-May-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Apr-21
PLACE OF ACCIDENT : AYE, SINGAPORE (NEAR CLEMENTI EXIT)

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 3284 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HANRESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	✓ /
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM.	S/N \$ 1,200.00	✓ /
3	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250 /
4	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, LHS FRONT FENDER AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	2750 /
5	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND HINGES.	\$ 3,600.00	2200 1650 /
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ /
TOTAL LABOUR CHARGES		: \$ 10,522.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3284 A

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,016.00	✓	1612.80	
2	FRONT BUMPER FIXING PARTS <i>see in</i>	1	\$ 187.00	x		
3	FRONT BUMPER GUIDE - LH/RH <i>see in</i>	2	\$ 78.00	x		
4	FRONT BUMPER GRILLE - LOWER <i>cracked</i>	1	\$ 160.00	✓	128.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER <i>cracked</i>	1	\$ 297.00	x	237.60	
6	FRONT BUMPER CLOSING ELEMENT - LH/RH <i>2H cracked</i>	2	\$ 594.00	?	237.60	
7	FRONT BUMPER AIR GRILLE - LH/RH <i>see in</i>	2	\$ 376.00	x		
8	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,406.00	✓	1124.80	
9	RADIATOR GRILLE CLOSING ELEMENT <i>cracked</i>	1	\$ 191.00	?	152.40	
10	STICKER FOR AIR CONDITIONER <i>see</i>	1	\$ 8.00	✓	5.68	
11	SIGN ' CAUTION ' STICKER <i>see</i>	1	\$ 14.00	✓	10.88	
12	FRONT BUMPER FOAM COVER <i>cracked</i>	1	\$ 122.00	?	97.20	
13	FRONT BUMPER FOAM <i>cracked</i>	1	\$ 189.00	?	151.20	
14	FRONT BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 195.00	?	636	
15	FRONT FENDER - LH <i>cracked</i>	1	\$ 851.00	✓	680.40	
16	FRONT FENDER POP RIVET <i>on</i>	8	\$ 27.00	✓	21.12	
17	FRONT FENDER ATTACHEMENT PARTS <i>see in</i>	1	\$ 72.00	x		
18	FRONT FENDER BRACKET - LH FRONT <i>cracked</i>	1	\$ 48.00	✓	37.68	
19	FRONT FENDER BRACKET - LH REAR <i>see in</i>	1	\$ 28.00	x		
20	FRONT FENDER CLOSING ELEMENT - LH <i>Not see</i>	1	\$ 62.00	?	x	
SUB-TOTAL SPARE PARTS		:	\$ 7,521.00			

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3284 A

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT FENDER BRACE - LH <i>Not New</i>	1	\$ 96.00	<i>+</i>	
22	FRONT WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 169.00	<i>+</i>	
23	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 57.00	<i>+</i>	
24	LED HEADLIGHT - LH <i>Cracked</i>	1	\$ 5,455.00	<i>✓</i>	4364
25	POWER MODULE FOR MAIN LIGHT <i>new</i>	1	\$ 758.00	<i>+</i>	
26	CONTROL UNIT FOR LIGHT CONTROL <i>new</i>	1	\$ 557.00	<i>+</i>	
27	LED WITH HEAT SINK <i>new</i>	1	\$ 733.00	<i>+</i>	
28	HEADLIGHT HOSE - LH <i>new</i>	1	\$ 40.00	<i>+</i>	
29	HEADLIGHT WASHER CYLINDER - LH <i>Not New</i>	1	\$ 142.00	<i>+</i>	
30	HEADLIGHT WASHER HOSE <i>new</i>	1	\$ 68.00	<i>+</i>	
31	BONNET <i>Dented</i>	1	\$ 2,745.00	<i>✓</i>	2196
32	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 165.00	<i>+</i>	
33	BONNET HINGE - LH/RH <i>new LH Bent.</i>	2	\$ 124.00	<i>+</i>	4888
34	BONNET EDGE PROTECTION <i>new</i>	1	\$ 28.00	<i>✓</i>	12
35	BONNET CATCH HOOK - UPPER <i>new</i>	1	\$ 90.00	<i>+</i>	
36	BONNET LOCK STRIKER - LH/RH <i>new</i>	2	\$ 220.00	<i>+</i>	
37	BONNET LOCK - LH/RH <i>new</i>	2	\$ 427.00	<i>+</i>	
38	BONNET LOCK BOWDEN CABLE <i>new</i>	1	\$ 58.00	<i>+</i>	
39	BONNET SOUND ABSORBER <i>Not New</i>	1	\$ 219.00	<i>+</i>	
40	FRONT LOCK CARRIER <i>Cracked</i>	1	\$ 727.00	<i>✓</i>	581.60
SUB-TOTAL SPARE PARTS			\$ 12,878.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 3284 A

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	INTAKE AIR GUIDE - LOWER <i>2 x m</i>	1	\$ 56.00	<i>+</i>
42	INTAKE AIR GUIDE COVER	1	\$ 29.00	<i>+</i>
43	INTAKE AIR GUIDE <i>new</i>	1	\$ 20.00	<i>+</i>
44	A/C CONDENSER	1	\$ 529.00	<i>+</i>
45	A/C CONDENSER SEAL RING	2	\$ 20.00	<i>+</i>
46	RADIATOR	1	\$ 951.00	<i>+</i>
47	ADDITIONAL RADIATOR	1	\$ 859.00	<i>+</i>
48	RADIATOR BRACKET - LOWER	2	\$ 82.00	<i>+</i>
49	COOLANT <i>new</i>	1	\$ 179.00	<i>✓</i>
50	RADIATOR AIR GUIDE - LH <i>crushed</i>	1	\$ 25.00	<i>19.44</i>
51	WASH WATER RESERVOIR <i>Deformed</i>	1	\$ 206.00	<i>164.40</i>
52	WASH WATER RESERVOIR SEAL <i>new</i>	1	\$ 8.00	<i>+</i>
53	BONNET CATCH HOOK - LOWER <i>new</i>	1	\$ 63.00	<i>+</i>
54	FRONT NUMBER PLATE <i>Dented</i>	S/N	\$ 60.00	<i>✓</i>
55	SUNDRIES <i>new</i>		\$ 300.00	<i>? 25.60</i>
TOTAL SPARE PARTS		:	\$ 23,786.00	
TOTAL LABOUR CHARGES		:	\$ 10,522.00	
GRAND TOTAL		:	\$ 34,308.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *04/05/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 09 Days*
llg.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKY Auto Consultants hence notify
the Repairer of the following:

- Survey before/after spray painting
- Spray damaged parts during resurvey
- All prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Structural modification is allowed
- Supplementary items must be resurveyed and subject to final approval from Insurer.

Authorised by Repairer

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0381/2021/CCS
7-May-21
CHANG
1 of 1
SMN 3284 A
AUDI A3 SPORTBACK 1.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	SIGNAL HORN - LH <i>cracked</i>	\$ 200.00	✓ 159.60
GRAND TOTAL		\$ 200.00	

For Premium Automobiles Pte Ltd

Adrian Ling
07/05/21
SL



Authorised Signature