

REPAIR ESTIMATE

MVA: MS. LOKE YY

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tamphi 97495745
wp 3/8/21 @ 1pm
c/s Resumy after repair
tamphi c/khantawun
2 days

Date:

Date/Time: 03.05.2021 11:07

Page :

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4076651

JC NO.:305466

| | | | |
|-------------------|--------------------------------|------------------------------|---------------|
| CUSTOMER | | REGN NO.: SHD3440C | MILEAGE |
| MR/MS | COMFORT TRANSPORTATION PTE LTD | MAKE: | FUEL |
| CUSTOMER NO. | 7010045 | TOYOTA | E.....1/2.... |
| ADDRESS | 383 SIN MING DRIVE | MODEL | DATE/TIME IN |
| | Singapore SINGAPORE 575717 | PRIUS HYBRID(G4)03 | 05.2021 04 |
| TEL. (R) | 65508755 | YR OF MANU. | TARGET DATE |
| (P) | (O) | 30.05.2017 | |
| DISCOUNT CARD NO. | | CHASSIS CODE | COMPLETION DA |
| | | JTDKB3FUX03557611 | |


Accident Date: 02.05.2021
NATURE: 3P 02.05.2021

JOB DESCRIPTION

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Name:

I/C No.:

Vehicle No.: **SHD3440C**

YY CHINA

Exit Pass

Vehicle No.:

SHD3440C

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard