



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 3208J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (N)	TORN	1,920.00	1,330.00
18	REAR BUMPER RIVETS @\$6.00 (N)	NECESSARY	108.00	30.00
1	REAR BUMPER BASIC CARRIER (N)	CRACKED	305.00	145.00
1	REAR BUMPER GRILLE (RH) (N)	CUT	155.00	155.00
1	REAR BUMPER LATERAL BRACKET (RH) (N)	NOT NECESSARY	375.00	-
1	REAR BUMPER REFLECTOR (RH) (N)	NOT NECESSARY	285.00	-
1	REAR BUMPER LOWER (RH) (N)	NOT NECESSARY	264.00	-
1	REAR BUMPER LOWER LATERAL SUPPORT (RH) (N)	NOT NECESSARY	205.00	-
1	REAR BUMPER REINFORCEMENT (N)	NOT NECESSARY	710.00	-
2	REAR BUMPER REVERSE SENSOR @\$430.00 (N)	NOT NECESSARY	860.00	-
2	REAR BUMPER REVERSE SENSOR O-RING @\$22.00 (N)	NOT NECESSARY	44.00	-
1	REAR FENDER (RH) (N)	NOT NECESSARY	2,490.00	-
1	REAR FENDER INNER SHIELD (RH) (N)	NOT NECESSARY	471.00	-
4	REAR FENDER INNER SHIELD RIVET @\$6.00 (N)	NOT NECESSARY	24.00	-
	LESS 10% DISCOUNT		-	-166.00
			8,216.00	1,494.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING SYSTEM.	NOT NECESSARY	120.00	-
	TO APPLY UNDERSEALING ON AFFECTED AREAS.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIX REVERSE SENSOR WITH WIRE HARNESS.		120.00	50.00
	TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC.		880.00	250.00
	TO RESPRAY ON AFFECTED AREAS.		440.00	250.00
			1,680.00	550.00
<b>GRAND TOTAL</b>			<b>9,896.00</b>	<b>2,044.00</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,600.00</b>
---	--	--	-----------------

Report Ref No. CS/INC21005471/Avf3n2

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**