

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref:	CS/INC21005472/Uvf3n2	
	73 BRAS BASAH R #05-01 NTUC TRAI 189556	COAD DE UNION HOUSESINGAPORE	Date:	17/05/2021	
	ATTN: CHARLOTT	E	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBH 3461S	Veh. Inspected	SMH 550H	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1128479-002	Excess (\$)	0.00	
	Assign From	THERESA VIMALA	Assign Date	05/05/2021	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ CLA180 (A)	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	WDD1173422N685804	Colour	WHITE	
	Odometer	64486 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/40 R18	YOKOHAMA	7 mm	
	L/H Front Tyre	225/40 R18	YOKOHAMA	7 mm	
	R/H Rear Tyre	225/40 R18	YOKOHAMA	7 mm	
	L/H Rear Tyre	225/40 R18	YOKOHAMA	7 mm	
4.	1. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND N/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/04/2021	Inspect Date / Time	05/05/2021 (10:27 AM)	
	Survey held at	T K LEE AUTOMOTIVE PTE LTD			
		NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				