

DAR ALG Xiao Chen.

SMK5795U.

Front Bumper	✓	Distorted
Front Bumper Clips	✓	Nec
Front Bumper Side Holder LH.	✓	Distorted.
Front Bumper Sponge	✓	Crushed
Front Bumper Reinforcement.	✓	Bent
Front Bumper Reinforcement Bracket LH.	✓	Bent
Front Bumper Tow Cover	✓	Deformed
Front Bumper Fog Lamp	✓	Crushed
Front Bumper Day Running Light.	✓	Crushed
Front Bumper Day Running Light Garnish.	✓	Distorted
Front Bumper Lower Grille.	✓	Deformed
Front Bumper Undercover	✓	Deformed
Front Bumper Undercover Clips.	✓	Nec
Front Bumper Logo.	✓	Nec

SMK 57954.

Front Grille.	✓	cracked
Front Grille Clips.	✓	ru
Headlamp LH.	✓	smashed
Front Fender LH.	✓	Distorted
Front Fender Inner Shield LH	✓	torn
Front Fender Inner Shield Clips.	✓	ru
Front Fender Emblem LH.	✓	ru
Front Fender Glass Moulding LH	✓	ru
Front Fender Glass Sealant LH.	✓	ru
Front Fender Bracket LH.	✓	Best
Front Fender Wheel House LH.	X	Repair
Front LH Door	X	Repair
Bonnet	X	Repair
Bonnet Hinge x 02.	✓	Best.

SMK 579SU.

Front Support Panel.	✓	Distorted
Fuse Box.	✓	Crushed
Front LH Wheel Rim.	✓	Lt
Front LH Wheel Rim Cover.	✓	Lt
Front LH Shock Absorber.	✓	Bent
Front LH Knuckle Arm.	✓	Damaged.
Front LH Wheel Hub c/w Bearing.	✓	Damaged
Front LH Lower Arm.	✓	Bent.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
Signature:
Date:

10 Days.

Adrian King,
2/8 *[Signature]*