

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD CS3/ASM21005480/T1vce2 Ref: 8 SHENTON WAY #24-01 AXA Date: 17/05/2021 **TOWERSINGAPORE 068811** ATTN: PAY DANIEL Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) SHB 7950G Insured Veh. SMD 9888X Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. S1M039CP Excess (\$) 0.00 PAY DANIEL 04/05/2021 Assign From Assign Date **Vehicle Particulars & Condition** 2. HONDA VEZEL HYBRID Make & Model 1496 c.c HIDDEN 2017 Year of Reg. Engine No. RU31214933 RED Chassis No. Colour Odometer 78501 KM Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 225/50 R18 YOKOHAMA 6 mm YOKOHAMA L/H Front Tyre 225/50 R18 6 mm 225/50 R18 YOKOHAMA R/H Rear Tyre 6 mm YOKOHAMA L/H Rear Tyre 225/50 R18 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 03/05/2021 Inspect Date / Time 05/05/2021 ( 02:07 PM ) Accident Date MERLIN MOTOR & ENGINEERING WORKS Survey held at BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #03-13 AMK AUTOPOINT SINGAPORE 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000 5b. **Estimate Days of Repair** 

Report Ref No. CS3/ASM21005480/T1vce2

Inspected By

MOHAMAD TAUFIKH

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

6 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser

M.MATAI, AMSAE-A
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.