



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 8599B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (SN)	TO REPAIR SEE LABOUR	2,832.00	-
1	REAR BUMPER LOWER GUIDE SECTION - RH (SN)	NOT NECESSARY	63.00	-
2	REAR BUMPER UPPER GUIDE SECTION - LH / RH (SN)	NOT NECESSARY	90.00	-
1	REAR BUMPER PARKING AID SENSOR (SN)	NOT NECESSARY	244.00	-
4	REAR BUMPER SEAL RING (SN)	NOT NECESSARY	14.00	-
1	REAR DOOR - RH (SN)	TO REPAIR SEE LABOUR	4,178.00	-
1	REAR DOOR SEAL BRACKET - RH (SN)	NOT NECESSARY	42.00	-
1	REAR DOOR OUTER DOOR SEAL - RH (SN)	NOT NECESSARY	172.00	-
1	REAR DOOR ATTACHMENT PARTS - RH (SN)	NOT NECESSARY	352.00	-
1	REAR DOOR CATCH (SN)	NOT NECESSARY	120.00	-
1	REAR DOOR ATTACHMENT PARTS (SN)	NOT NECESSARY	130.00	-
1	REAR DOOR ADHESIVE TAPES (SN)	NOT NECESSARY	58.00	-
1	SILL PANEL TRIM ATTACHMENT PARTS - RH (SN) (NPA)	NOT NECESSARY	-	-
1	ALUMINIUM RIM - RH (SN)	TO REPAIR SEE LABOUR	1,652.00	-
1	SUNDRIES (SN)	NOT NECESSARY	200.00	-
			10,147.00	-
<u>LABOUR</u>				
TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.			360.00	360.00
TO DISMANTLE AND RENEW BUMPER, REPAIR REAR RH FENDER, RH SILL PANEL AND REAR RH DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR DOOR - RH AND ALUMINIUM RIM - RH.			3,800.00	1,200.00
TO RESPRAY REAR BUMPER, REAR RH FENDER, REAR RH DOOR AND RH SILL PANEL.			3,800.00	3,200.00
TO REPLACE REAR RH RIM AND CONDUCT ALIGNMENT TEST.			280.00	240.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			8,432.00	5,192.00
GRAND TOTAL			18,579.00	5,192.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				5,192.00

Report Ref No. CS/AWA21005481/Avf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.