

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

05th MAY 2021

TP Chinn.
Insulin.

Accident date: 03RD MAY 2021

Estimated repair cost for vehicle no: SLH1170B HONDA VEZEL 1.5 '2016

S/n	Qty	Items	U/price	Amount
1	1	Front head lamp -LH <i>cracked</i>		\$1,785.20 ✓
2	1	Front head lamp lower bracket-LH <i>new</i>		\$112.20 X
3	1	Front bumper <i>Distorted</i>		\$950.00 <i>864.</i>
4	2	Front bumper side bracket <i>LH Dmg</i>	\$125.20	\$250.40 <i>35</i>
5	10	Front bumper clips <i>new</i>	\$5.00	\$50.00 <i>30.</i>
6	1	Front bumper number plate <i>new</i>		\$50.00 X
7	1	Front bumper reinforcement <i>Dented</i>		\$484.00 <i>321.</i>
8	1	Front bumper mud shield -LH <i>new</i>		\$112.00 X
9	1	Front bumper center lower garnish <i>Dented</i>		\$220.10 ✓
10	1	Front bumper center lower cover <i>new</i>		\$295.10 X
11	1	Front Bumper Fog lamp-LH <i>new</i>		\$252.10 X
12	1	Front Bumper Fog lamp cover-LH <i>Dented</i>		\$125.20 ✓
13	1	Front Grille <i>cracked</i>		\$385.00 ✓
14	1	Front Grille emble logo <i>new</i>		\$56.00 ✓
15	10	Front Grille clips <i>new</i>	\$5.00	\$50.00 <i>20</i>
16	1	Front support panel <i>new</i>		\$952.00 X
17	2	Front support panel side bracket <i>new</i>	\$65.20	\$130.40 X
18	1	Front fender-LH <i>Dented</i>		\$685.00 ✓
19	1	Front fender cowling-LH <i>torn</i>		\$185.20 ✓
20	10	Front fender cowling clips <i>new</i>	\$5.00	\$50.00 <i>30.</i>
21	1	Front lower arm-LH		\$285.00 X
22	1	Front knuckle arm-LH	<i>4641.70</i>	\$315.00 X
23	1	Front knuckle arm bearing-LH	<i>3713.36</i>	\$138.00 X
24	1	front Tyre - LH		\$300.00 X
25	1	front rim -LH		\$300.00 X

Subtotal :- \$8,517.90

Labour charges

To remove & re-fix cushion

1120 \$120.00 X

To remove & re-fix front undercarriage

\$280.00 X

Wheel alignment (computer)

\$120.00 X

To Check Wiring System

Supplementary: 423.20 \$80.00 *30*

Tuff Kote

LKK Auto Consultants hence notify the Repairer of the following:

total: 5256.56 \$120.00 *40*

Towing charges

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

\$100.00 *50*

Panel beating

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

h/s: 4.2K \$800.00 *600*

Spray painting

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

04 Days \$800.00 *400.*

Subtotal :- \$2,420.00

Total:- \$10,937.90

Acknowledged by Repairer
Signature:
Date:

Supplementary S L H 1170B.

Front LH Fender Arc Garnish.	Distorted	165	/
Front LH Fender Arc Garnish clips	re	30.	/
Front Grille Bracket	auhd	76	/
Air Resonator	auhd	180.50	/
Air Duct.	Dehd	77.50.	/

529

km 20% : 423.20.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: