

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/GRB21005489/BQF3E2

**Date:** 07/07/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** SLF4835H **Insured Vehicle No :** SMY8984Y  
Date of Loss: 29/04/2021 Nature of Claim: TP Claim No: MFL2021D0002005

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF4835H**  
Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4028449  
Reg. Date: 29/08/2016 (Man. Year: 2015) Chassis No: RU11108446  
Colour: Blue Odometer: 82483 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,698.56	976.48	1,722.08	63.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	2,430.00	640.00	1,790.00	73.66
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,128.56</b>	<b>1,616.48</b>	<b>3,512.08</b>	<b>68.48</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,128.56</b>	<b>1,300.00</b>	<b>3,828.56</b>	<b>74.65</b>

### INSPECTION

Date of Assignment: 05/05/2021  
Date Inspected: 06/05/2021 Inspected At: Sze Kang Automobile Spraying Services (HQ)  
BLK 10 ANG MO KIO INDUSTRIAL PARK 2A,  
#03-17  
Singapore 568047  
Estimated Period of Repair: 4.0 days

**Adjuster:** Lim Teow Guan

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jul 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF4835H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Dented	1,056.40 FL	*935.20 FL
2	1		*SET REAR RH DOOR BLACK STICKER	Necessary	65.40 FL	*30.00 FL
3	1		*SET REAR RH DOOR WEATHERSTRIP	Not Damaged	185.50 FL	*- FL
4	1		*REAR RH DOOR INNER TRIM BOARD	Serviceable	584.00 FL	*- FL
5	1		*SET REAR RH DOOR INNER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
6	2		*REAR RH DOOR HINGE (TOP & BOTTOM)	Serviceable	96.00 FL	*- FL
7	1		*REAR RH DOOR GLASS REGULATOR & MOTOR	Not Damaged	412.30 FL	*- FL
8	1		*RH ROCKER PANEL	Not Damaged	432.60 FL	*- FL
9	1		*RH ROCKER PANEL OUTER COVER	Broken	401.00 FL	*225.40 FL
10	1		*SET RH ROCKER PANEL OUTER COVER CLIPS	Necessary	80.00 FL	*30.00 FL
					Sub Total (\$\$)	3,373.20 1,220.60
					- List Item Discount on L Items 20.00/20.00% (\$\$)	674.64 244.12
					Total Parts (\$\$)	2,698.56 976.48

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS	New	1,100.00	300.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	300.00
3	TO REMOVE, REFIX REAR RH DOOR FITTINGS TO FACILITATE REPAIRS	New	100.00	40.00
4	TO CHECK WIRINGS	New	50.00	0.00
5	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST	New	80.00	0.00
6	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,430.00</b>	<b>640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >