4	<	1	of 2 ?	>	ÞΙ	$\bigcirc$	<b>⊕</b>	100%	~	<sub>E</sub>	Find   Next	



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	ale Des Experts En	Automob	ile									
	LONPAC INSURAN	ICE BHD		Ref:	CS3/LPC21005496/R1vf3									
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	05/05/2021									
				Code:	LPC2									
	Policy Particulars :- (THIRD PARTY CLAIM)													
	Insured Veh.	XD 4626M	Veh. Inspected		SJL 3449M									
	Policy No.		Coverage (\$)		0.00									
	Claim No.		Excess (\$)		0.00									
	Assign From	GERALD POH	Assign Date		05/05/2021									
<u>.</u>		Vehicle Partic	ulars & Condition	on										
	Make & Model		c.c		0									
	Engine No.	HIDDEN	Year of Reg.											
	Chassis No.		Colour											
	Odometer	-	Steering											
	Brakes		Modification											
	General													
3.		Condition	ons of Tyres											
		Size	Make		Balance									
	R/H Front Tyre				mm									
	L/H Front Tyre				mm									
	R/H Rear Tyre				mm									
	L/H Rear Tyre				mm									
l.		Description of Damages												
5.	1	03/05/2021	Information		05/05/0004									
	Accident Date		Inspection Dat		05/05/2021									
	Survey held at	1 BUKIT BATOK CRESCENT #0	3-25, WCEGA PLA	ıΖΑ										
	Repairer -													
5a.	Remarks													
	B) THE REPAIR ES	ON WAS CONDUCTED ON A "WI' STIMATE WAS NOT PRESENTED 'AS TOLD TO PREPARE THE ES' EASE FIND DAMAGED VEHICLE	AT THE TIME OF TIMATE.	INSPEC										