

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -20%	
SN	
Labour	
Total	
Lump Sum	
ERV	40K

TO: AXA

Vehicle No : SGW 2299 M

Make & Model : HONDA CIVIC

DATE: 4/5/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT DOOR LH	1	\$ 924.70	\$ Ry 924.70
6	FRONT DOOR INNER LOCK LH	1	\$ 312.00	\$ Xm 312.00
7	FRONT DOOR LOCK CATCH LH	1	\$ 56.00	\$ Xm 56.00
8	FRONT DOOR WEATHERSTRIP LH	1	\$ 198.00	\$ Xm 198.00
	FRONT DOOR LOWEW RUBBER LH	1	\$ 75.00	\$ ent 75.00
9	REAR DOOR LH	1	\$ 717.50	\$ di 717.50
10	REAR DOOR BLACK STICKER LH	2	\$ 45.00	\$ re 90.00
11	REAR DOOR OUTER MOULDING LH	1	\$ 198.00	\$ Xm 198.00
12	REAR DOOR HINGE LH	2	\$ 97.00	\$ Xm 194.00
13	REAR DOOR CHECKER LH	1	\$ 127.90	\$ Xm 127.90
14	REAR DOOR INNER LOCK LH	1	\$ 298.50	\$?bt 298.50
15	REAR DOOR LOCK CATCH LH	1	\$ 56.00	\$ Xm 56.00
16	REAR DOOR WEATHERSTRIP LH	1	\$ 198.00	\$ ent 198.00
17	REAR DOOR CHANNEL LH	1	\$ 96.00	\$ Xm 96.00
18	REAR DOOR CHANNEL SEAL LH	1	\$ 154.00	\$ Xm 154.00
19	REAR DOOR REGULATOR MOTOR LH	1	\$ 317.00	\$ Xm 317.00
20	REAR DOOR REGULATOR GEAR LH	1	\$ 177.20	\$?bt 177.20
21	REAR DOOR INNER TRIM LH	1	\$ 340.90	\$ Xm 340.90
22	REAR DOOR INNER STEP GARNISH LH	1	\$ 124.00	\$ Xm 124.00
23	ROCKER PANEL LH	1	\$ 602.70	\$ Ry 602.70
24	SIDE SKIRT LH	1	\$ 668.00	\$ de 668.00
25	REAR FENDER LH	1	\$ 794.00	\$ Ry 794.00
26	REAR FENDER INNER SHIELD LH	1	\$ 198.00	\$ de 198.00
27	REAR AIR VENT LH	1	\$ 100.00	\$ Xm 100.00
28	REAR ABSORBER LH	1	\$ 228.60	\$?bt 228.60
29	REAR LOWER ARM LH	1	\$ 171.60	\$ Xm 171.60

[illegible]

REMOVE AND INSTALL FRONT DOOR PART	\$ X ⁿⁿ 180.00
REMOVE AND INSTALL REAR DOOR PART	\$ 60 180.00
REMOVE AND INSTALL REAR WINDSCREEN	\$ X ⁿⁿ 250.00
REMOVE AND INSTALL CARPET, SEAT AND INTERIOR	\$ 60 450.00
REMOVE AND INSTALL REAR UNDER CARRIAGE <i>photo</i>	\$ 150 [?] 600.00
TO JACK AND REALIGNMENT CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ X ⁿⁿ 300.00
TO REPROGRAM, RESET AND CHECK ABS SYSTEM FUCTION	\$ X ⁿⁿ 600.00
TO CHECK FOUR WHEEL ALIGNMENT	\$ 80 100.00
	2120
LABOUR TOTAL	\$ 6,660.00

	Total Parts Cost	\$ 19,766.88
	Total Labour Cost	\$ 6,660.00
	Total Repair Cost	\$ 26,426.88

APPROVED DETAILS
 NO. OF WORKING DAYS
 PART BY PART OR LUMP SUM
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 FAX NUMBER

Tauphin 97495749
 WP' 6/5/21 @ 1250pm
 1/1 Rozumy after repair
 Tauphin @ (Khanh...)
 06 days

3502.96
 2670
 2120
 8292.96
 4586600
 # 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: