

Longal Ins. Sdn.
300 Beach Rd
#17-04/07 The Concourse
Spae 179 555 -

Date: 5/5/21

Attn.: Motor Claims Department

Dear Sir/Madam

RE: Accident involving vehicles SMF 5530T & XD 170PC

On 29/4/21 at Jurong Island


It is in my opinion that the above mentioned accident was caused solely by the negligence of the driver of the vehicle no: XD 170PC

As the above vehicle was insured by your insurance company at the material time of the accident. I would appreciate that you could kindly arrange your surveyor to survey my vehicle soonest possible at the following address :-

Kan Fook Sing Motor Workshop
61 Defu Lane 12
Singapore 539147
Tel : 67479560 (O)

Thank you

Yours faithfully

A large, stylized handwritten signature in black ink, consisting of several overlapping loops and a long horizontal stroke extending to the right.



簡福星嘍哆王廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
 E-mail: ryan@kanfs.net/ patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

LONPAC INSURANCE BHD
 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE
 199555

DATE : 05-05-2021

VEHICLE NO. : SMF5530T
 ACCIDENT DATE : 29-04-2021 17:45
 THIRD PARTY REF. : XD1709C

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SMF5530T MAZDA 5

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BUMPER	420.00
2	10	REAR BUMPER CLIP@\$2.00	20.00
3	1	REAR FENDER WHEEL ARCH GARNISH RH	90.00
4	1	REAR DOOR RH	510.00
			<hr/>
			1,040.00
ADD 20 %			208.00
TOTAL (A)			<hr/>
			1,248.00

LABOUR CHARGES

1	1	TO REMOVE/REFIT REAR FENDER INNER GARNISH	60.00
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	550.00
3	1	SPRAYPAINTING CHARGES	620.00

TOTAL (D)			<hr/>
			1,230.00
ESTIMATE TOTAL			<hr/>
			2,478.00