

# CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W GST Reg No: 202026492W

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date : 04/05/2021

Estimated repair cost for vehicle no: SJP1485A HONDA STREAM 1.8XA

CHASSIS: RN61087629 (2008)

TPAIG  
Xiao Tong

04/05/2021

S/N	Qty	Items	U/price	Amount	
1	1	REAR BUMPER <i>Dehnd</i>	\$698.60	\$698.60	✓
2	1	REAR BUMPER LOWER BRACKET LH <i>3 Best</i>	\$70.40	\$70.40	✓
3	1	REAR BUMPER LOWER BRACKET RH	\$70.40	\$70.40	✓
4	1	REAR BUMPER SIDE RETAINER LH <i>3 per</i>	\$43.80	\$43.80	✓
5	1	REAR BUMPER SIDE RETAINER RH	\$43.80	\$43.80	✓
6	1	REAR BUMPER TOW COVER <i>culd</i>	\$38.20	\$38.20	✓
7	1	REAR TAILGATE <i>Dented</i>	\$1,398.50	\$1,398.50	903 ✓
8	1	REAR TAILGATE SHOCK ABSORBER LH <i>3 NP</i>	\$115.60	\$115.60	✓
9	1	REAR TAILGATE SHOCK ABSORBER RH <i>3 NP</i>	\$115.60	\$115.60	X
10	1	REAR TAILGATE OUTER GARNISH <i>3 NP</i>	\$347.60	\$347.60	X
11	1	REAR TAILGATE INNER TRIM BOARD <i>culd</i>	\$456.30	\$456.30	285 ✓
12	1	REAR TAILGATE TRIM BOARD HANDLER <i>3 NP</i>	\$28.60	\$28.60	X
13	1	REAR TAILGATE EMBLEM STREAM <i>3 NP</i>	\$69.80	\$69.80	✓
14	1	REAR TAILGATE LOGO <i>3 NP</i>	\$70.80	\$70.80	X
15	1	REAR TAILGATE LOCK <i>Dented</i>	\$385.90	\$385.90	245 ✓
16	1	REAR TAILGATE WEATHER STRIPE <i>3 NP</i>	\$185.40	\$185.40	✓
17	1	REAR TAILGATE WIPER MOTOR <i>3 NP</i>	\$589.00	\$589.00	+
18	1	REAR WINDSCREEN GLASS MOUDLING <i>3 NP</i>	\$228.30	\$228.30	125 ✓
19	2	REAR NUMBER PLATE LAMP <i>3 NP</i>	\$194.20	\$338.40	X
20	1	REAR TAILLAMP LH <i>culd</i>	\$667.40	\$667.40	368 ✓
21	1	REAR TAILLAMP SIDE COVER LH <i>3 NP</i>	\$25.00	\$25.00	+
22	1	REAR TAILLAMP RH	\$667.40	\$667.40	368 ✓
23	1	REAR TAILLAMP SIDE COVER RH <i>3 NP</i>	\$25.00	\$25.00	+
24	1	REAR END PANEL <i>Dented</i>	\$625.00	\$625.00	425 ✓
25	1	REAR END PANEL TOP GARNISH <i>Dehnd</i>	\$267.80	\$267.80	182 ✓
26	1	REAR END PANEL CROSS MEMBER <i>Dented</i>	\$343.60	\$343.60	+
27	1	REAR END PANEL CENTER GARNISH <i>3 NP</i>	\$125.60	\$125.60	+
28	1	REAR FLOOR TOP BOARD LH <i>3 NP</i>	\$348.80	\$348.80	+
29	1	REAR FLOOR TOP BOARD RH <i>3 NP</i>	\$348.80	\$348.80	+

30	1	REAR FLOOR PANEL <i>tyre</i>	\$1,159.00	\$1,159.00	+
31	1	REAR TOOLS COMPARTMENT LINING <i>x2 of new</i>	\$295.20	\$295.20	+
32	1	REAR SPARE TYRE CARRIER <i>new</i>	\$347.00	\$347.00	+
33	1	REAR SPARE TYRE CARRIER BRACKET <i>3 of new</i>	\$321.00	\$321.00	+
34	1	REAR SPARE TYER BOLT <i>1 of new</i>	\$74.00	\$74.00	+
		REAR EXHUAST MUFFLER <i>new</i>	\$965.00	\$965.00	+
		REAR FENDER INNER TRIM BOARD LH <i>new</i>	\$597.60	\$597.60	385
		REAR FENDER INNER TRIM BOARD RH <i>new</i>	\$597.60	\$597.60	+

4850  
3880

TOTAL :	\$13,095.80
LESS 20 %	\$2,619.16
SUB-TOTAL :	\$10,476.64

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount	
1	1	REAR BUMPER CLIPS <i>new</i>	\$6.50	\$65.00	30
2	1	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	\$6.50	\$65.00	10
3	4	REAR TAILLAMP CLIPS <i>new</i>	\$4.50	\$18.00	+
4	1	REAR END PANEL SEALANT <i>new</i>	\$80.00	\$80.00	60
5	1	REAR FLOOR PANEL SEALANT <i>new</i>	\$80.00	\$80.00	+
6	1	SEALANT <i>new</i>	\$100.00	\$100.00	+
7	1	REAR TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	\$6.50	\$65.00	✓
			TOTAL:	\$473.00	
			TOTAL PARTS :	\$10,949.64	

165

**Labour charges**

1	LABOUR FOR PANEL BEATING	\$1,200.00	80
2	LABOUR FOR SPRAYPAINTING	\$1,000.00	80
3	WIRING CHECK	\$100.00	30
4	TO APPLY RUST PROOF ON ACCIDENT AREAS	\$150.00	60
5	TO APPLY TUFF COATING ON ACCIDENT AREAS	\$150.00	+
6	LABOUR FOR REMOVE & REFIX CUSHION/UPHOLSTERY/ROOF LINING TO FACILITATE THE REPAIR	\$300.00	80
7	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING	\$300.00	80

8 TO CONDUCT WATER CHECK LEAKAGE

1970

\$120.00 x

9 LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS

\$150.00 / 20

Subtotal :- \$3,470.00

Total:- \$14,419.64

total: 6015/2

4/s: 4.8k

06 Days

4.8k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: