

Faster
memory
speedPrecision
touchpadFaster
wirelessGigabit
Ethernet

• Intel® Celeron® processor N4020

• Intel® UHD Graphics

• 4 GB DDR4 Memory

• 128GB SSD

AERO GARAGE PTE LTD

Blk 160, Sin Ming Drive, #08-07 Sin Ming AutoCity, Singapore 575722
Tel : 6266 9511 Fax : 6266 9512

Vehicle No : SJP7777T
Vehicle Model : Toyota Vellfire

Date : 07.05.2021

Estimate Repair Cost

No.	Qty	Parts List Items		
1	1	Rear bumper <i>1217</i>	<i>Buc/M</i>	\$ 1,449.95 ✓
2	2	Rear bumper brackets	\$	124.20 X
3	2	Rear bumper retainers	\$	220.70 X
4	1	Rear bumper towing cover	\$	69.40 X
5	2	Rear bumper reflectors	\$	196.80 X
6	1	Rear bumper reverse sensor wiring	\$	455.89 X
7	1	Rear bumper electrical antenna assy	\$	201.23 X
8	1	Rear bumper side lower cover LH	\$	210.40 X
9	1 set	Rear bumper clips	\$	40.00 ✓
10	2	Side bumpers	\$	402.70 X
11	2	Side bumper retainers	<i>1500</i>	\$ 232.20 ✓
12	1	Rear tailgate <i>1718</i>	<i>R1</i>	\$ 1,985.50 ✓
13	1	Rear tailgate chrome gamish	<i>Sm</i>	\$ 890.95 X
14	1	Rear tailgate "ALPHARD" emblem	\$	116.20 ✓
15	1	Rear tailgate lock <i>480</i>	\$	509.65 ✓
16	1	Rear tailgate number plate lamp	\$	116.90 X
17	2	Rear tailgate lamps	<i>Sm</i>	\$ 1,396.20 X
18	2	Rear tailgate side sensors	<i>Sm</i>	\$ 1,018.80 X
19	1	Rear tailgate inner trim	\$	898.40 X
20	1	Rear tailgate hinges	\$	176.20 X
21	1	Rear tailgate dampers	\$	598.80 X
22	1	Rear tailgate weatherstrip	\$	399.45 X
23	2	Taillamps	<i>Sm</i>	\$ 1,596.90 X
24	1	Rear end panel <i>745.20</i>	\$	799.70 ✓
25	1	Rear end panel top gamish <i>299.10</i>	<i>my D.S</i>	\$ 398.10 ✓
26	1	Rear spare tyre top board	\$	781.40 X
27	1	Rear spare tyre compartment	\$	788.40 X
28	1	Immobilizer sensor	\$	510.40 X
29	1	Smart buzzer	\$	201.40 X
30	1	Rear spare tyre compartment cloth	\$	699.25 X
Total				\$ 17,486.07

Parts Special Nett Items

1	1	Rear number plate	\$	60.00 X
2	4	Reverse sensors	\$	800.00 X
			\$	860.00
Total Parts			\$	18,346.07

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 1,800.00	600
2	To putty and respray painting on affected areas.	\$ 1,500.00	600
3	To remove, replace rear tailgate fittings to facilitate repair.	\$ 300.00	600
4	To remove, replace rear windscreen glass.	\$ 250.00	1200
5	To remove, replace reverse sensor.	\$ 150.00	500
6	To check wiring and lightings.	\$ 80.00	200

Total Labour \$ 4,080.00

Total Parts and Labour \$ 22,426.07

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Acknowledged by Repairer

Signature:

Date: