

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorized
Pharmacy B4paim

\$15183.82 B4 excess 9 days

REPAIR ESTIMATE FOR GBJ 2454 J

List items		
1 pc.	Front bumper	Sm \$ 727.10 X
1 pc.	Front bumper LH inner bracket	R 292.10 X
1 pc.	LH headlamp ✓ 1145.10	CM 1,145.10
1 pc.	Front grille ✓	CM 673.10
1 pc.	Front grille centre "TOYOTA" logo ✓	Sm 97.10
1 pc.	Front wiper panel	R 258.10
1 pc.	Front body panel ✓	R 1,244.10
1 pc.	Front "DYNA" emblem ✓	Sm 84.10
1 pc.	Front LH side mirror garnish	Mr 192.30
1 pc.	Front LH side mirror assy ✓	my CM 695.40 X
1 pc.	Front LH corner panel ✓	my 258.20
1 pc.	Front windscreen moulding ✓	CM 248.22
1 pc.	Dashboard assy ✓	CM 980.60
1 pc.	Air con low pressure house	Sm 509.00 X
1 pc.	Air con evaporator unit	(Hv) CM 1,089.00
1 pc.	Air con blower unit	Sm 1,135.10 X
1 pc.	Heater unit	CM 2,017.10
1 pc.	Front LH door ✓	Bu 1,450.45
1 pc.	Front LH door front pillar outer ✓	R 485.10
1 pc.	Front LH door front pillar inner	R 405.00
1 pc.	Front LH door rear pillar ✓	R 660.00 X
1 pc.	Front LH door inner lock ✓	Net 509.00
2 pcs.	Front LH door hinge (Top & bottom) ✓	R 148.20
1 pc.	Front LH door checker	Sm 145.00 X
1 pc.	Front LH weatherstrip	Sm 169.40 X
1 pc.	Front LH door inner trim board ✓	Bu 728.10
1 set.	Front LH door inner trim board clips	AN 50.00
1 pc.	Front LH door glass ✓	Shotton 408.10
1 pc.	Front LH door glass outer moulding ✓	Bu 115.10
1 pc.	Front LH door glass inner moulding	Sm Bu 110.12 X
1 pc.	Front LH door glass regulator ✓	Di 395.00
1 pc.	Front LH door glass regulator motor	Sm 509.00 X
1 pc.	Front LH door glass channel	Sm 145.10 X
1 pc.	Front cabin rear railing	R 685.40 X
1 pc.	Front LH step panel	R 435.10
1 pc.	Front LH step garnish ✓	CM 218.10
		\$ 19,416.99
Less 25%		4,854.25
		\$ 14,562.74
		\$ 14,562.74

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Special nett items

1 pc. Front LH door lower company black sticker

\$ *Na* 40.00 *25m* SN

Labour

1. Towing charges.
2. Labour Charges for remove/refit, cutting/welding and replacement of damages.
3. To putty and spray Spray Paintings charges.
4. To remove, refit front windscreen glass.
5. To check wirings and lightings.
6. To remove, refit dashboard assy.
7. To remove, refit air con blower/evaporator unit, including refill air con gas.
8. To remove, refit brake booster pump, brake hoses/pipings, clutch hose and bleed systems.
9. To remove, refit front LH door fittings.

\$ 120.00 *60l*
2,000.00 *1600l*
2,000.00 *1600l*
140.00 *60l*
40.00 *30l*
250.00 *220l*
140.00 *100l*
nr 80.00 *X*
80.00 *60l*

Total \$ 19,452.74

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

SUPPLEMENTARY REPAIR ESTIMATE FOR TOYOTA DYNA - GBJ 2454 J

<u>Items</u>			
1 pc.	Air-con condenser assy ✓	By \$	950.30 ✓
1 pc.	LH Panel, instrument, LWR ✓	my car	279.90 ✓
		\$	1,230.20
Less 25%			307.55
Total		\$	922.65