

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7602L****AAD2105-***Not Authorized  
Accuracy B4 point*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**04 MAY 2021****SHB7602L****JTDKB3FU503081963****TOYOTA****PRIUS****03/05/2021****AIG****27/06/2019**

<b>PART</b>	<b>LIST</b>	
1 COVER, FRONT BUMPER	\$	516.00 ✓ DAM
1 GRILLE SUB-ASSY, RADIATOR	\$	346.00 X
1 GRILLE, RADIATOR, LOWER NO.1	\$	170.10 X
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	716.60 X
1 REINFORCEMENT, FRONT BUMPER, NO.2	\$	246.10 X
1 ABSORBER, FRONT BUMPER, LOWER	\$	132.70 X
1 ABSORBER, FRONT BUMPER ENERGY	\$	79.60 X
1 RETAINER, REAR BUMPER SIDE, LH	\$	116.50 X
1 BRACKET, FRONT BUMPER SIDE, LH	\$	59.30 X
1 UNIT ASSY, HEADLAMP, LH	\$	SVC 2,637.60 X
1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	960.50 X
1 LAMP ASSY, FOG, LH	\$	951.40 X
1 FENDER SUB-ASSY, FRONT LH	\$	977.80 X
1 FRONT FENDER EMBLEM LH	\$	54.60 ✓
1 LINER, FRONT FENDER, LH	\$	202.50 ✓
<b>TOTAL</b>	<b>\$</b>	<b>8,167.30</b>
<b>25%</b>	<b>\$</b>	<b>2,828.00</b>
	<b>\$</b>	<b>8,484.00</b>

**Special Nett**

1 RIM	\$	1,879.40 X
1 TYRE	\$	350.00 X
1 HUBCAP	\$	211.50 ✓
1 FRT FENDER CLIP	\$	65.00 ✓
1 FRONT NUMBER PLATE WITH MOULDING	\$	200.00 X
1SET FRONT FENDER LINER CLIP	\$	75.00 X
1SET FRONT BUMPER CLIP	\$	90.00 X
<b>TOTAL</b>	<b>\$</b>	<b>2,870.90</b>

**Trans-cab Auto Services Pte Ltd**

AAD2105-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7602L

**TOTAL PARTS \$ 9,530.50****LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion,  
Remove And Renewal Of Parts, Adjust And Realign The Same  
To remove and refit interior fittings, trimmings, garnish, fittings and  
other, to enable repair.

\$ 1,600.00 *2001*\$ *22* 380.00 *X*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *22* 240.00 *X*

To check steering geometry and computer wheel alignment

\$ 220.00 *601*

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 *4401*

To transfer of tire, rim and on wheel balancing.

\$ *22* 170.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *152***TOTAL \$ 4,380.00****Over All Total \$ 15,734.90****(PART-BY-PART) Repair Days***20 days**2 days*

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: