Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Adeline Chng Pei Wen Date: 02 Jun 2021

Preliminary Advice

Insured Vehicle No : SGD2282K

TP Vehicle No : SFP2281L Accident Date : 04/05/2021
Make : TOYOTA COROLLA ALTIS Assignment Date : 05/05/2021

Date of Inspection : 01/06/2021 Est. Duration of Repair : 4

Inspection At : LIM YEW BOO SPRAY PAINT CO (HQ)

NO. 176 SIN MING DRIVE #03-05, SIN MING IND EST

SINGAPORE 575645

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,313.96
Revised Amount	:S\$	1,943.00
Check Items (Estimated)	:S\$	551.43
Total	:S\$	2,494.43

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

)	let us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments: