

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref: CS3/LPC21005512/R1tf3e2	
300 BEACH ROAD		Date: 10/06/2021	
#17-04/07 THE CONCOURSESINGAPORE 199555		Code: LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	YN 1475L	Veh. Inspected	JJG 9813
Policy No.		Coverage (\$)	0.00
Claim No.	20/21/21/VC05/024534	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	05/05/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA INNOVA	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	PN111NV4008602142	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50Z R17	APLUS	6 mm
L/H Front Tyre	225/50Z R17	APLUS	6 mm
R/H Rear Tyre	225/50Z R17	APLUS	6 mm
L/H Rear Tyre	225/50Z R17	APLUS	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	04/05/2021	Inspection Date	07/05/2021
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			