

PAIR ESTIMATE*

VEHICLE NO: SH A6575T

DATE 02/05/21 12:00 AM

MAKE :

MODEL : HYUNDAI IONIQ G2

CHIANG /CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER <i>scr</i>			\$430.90
1	FRONT BUMPER CENTRE MOULDING <i>X</i> SVC			\$368.50
1	FRONT BUMPER BRACKET LH <i>X</i> SVC			\$28.00
1	FRONT HEADLAMP ASSY LH <i>X</i> SVC			\$1,993.65
1	FRONT FENDER LH <i>repair</i>			\$588.80
1	FRONT FENDER EMBLEM <i>rec</i>			\$26.60
1	FRONT BUMPER GRILLE LH <i>cut</i>			\$186.90
1	FRONT DAY LIGHT LH <i>X</i> SVC			\$642.50
1	FRONT WHEEL COVER LH <i>scr</i>			\$368.50
				\$4,634.35
				\$926.87
				\$3,707.48
				\$-
	Labour Charge			
	Panel Beating			350 \$750.00
	Spray Paint			500 \$600.00
	Reset front wheel alignment			\$60.00
	Check lighting			300 \$60.00
	TOTAL LABOUR			\$1,470.00
	ESTIMATE TOTAL			\$5,177.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUL
Hp 90010068
3 days
9/8
04/05/21
@ 1520
Resurvey before paint

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.