



**Section A - Accident Details**

Registration Number	SHC4741H
Case Reference Number	TAX/05/21/2006
Registration Date	22/1/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TOH TIOW BENG
Type of Accident	Side Swipe
Accident Date and Time	4/5/2021 11:50 AM
Accident Reported Date and Time	5/5/2021 9:48 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110800
Special Instruction to ARC, if any	TP / RIGHT WING MIRROR
Prepared Date and Time	5/5/2021 1:17 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,296.00	\$450.00
Total Spare Part Cost	\$5,135.13	\$982.87
Total Other Cost	\$600.00	\$60.00
<b>TOTAL COST</b>	<b>\$7,538.13</b>	<b>\$1,692.87</b>
<b>Lump Sum Total</b>	<b>\$7,550.00</b>	<b>\$1,700.00 (L/S)</b>
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	<b>Ang Bang Kien</b>	<b>STEVE CHEN (LKK) / ERGO</b>
ARC / Surveyor Sign Off Date	<b>06/05/2021 2:27 PM</b>	<b>06/05/2021 1:46 PM</b>
Signature		
Remarks		LUMPSUM REPAIR, TAKE AFTER SPRAY

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2105-0199	<b>Invoice Number</b>	
<b>Quotation Date</b>	18.05.2021	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**
**Part 1 - Labour Works**

<b>Job Scope</b>	<b>Quotation from AR</b>	<b>Adjusted by Surveyor, if applicable</b>
TO REPAIR RH PORTION	\$507.00	\$200.00
<b>Total Labour</b>	<b>\$507.00</b>	<b>\$200.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
RESPRAY MIRROR COVER RH	\$180.00	\$50.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,296.00</b>	<b>\$450.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$30.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$10.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$600.00</b>	<b>\$60.00</b>

**Part 4 - Spare Parts / Material Usage**

<b>Part Number</b>	<b>Portion</b>	<b>Stock Number</b>	<b>Part Name</b>	<b>Quantity</b>	<b>List Price (\$)</b>	<b>Discount (%)</b>	<b>Final Price (\$)</b>	<b>Estimator Approved</b>	<b>Surveyor Approved</b>
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair
		52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given
		81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given
		76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given
		81130-47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00	Replace	Not Given
		53801-47050	FENDER FRT/RH	1.00	\$723.40	100.00	\$0.00	Replace	Repair
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		53875-47030	FENDER LINER FRT/RH	1.00	\$171.70	25.00	\$128.78	Replace	Replace
		53851-47040	FENDER LINER PAD, FR WHEEL. RH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given

R  
X  
X  
X  
X  
X  
X  
X  
X  
X  
R  
✓  
✓  
X

# SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 18/05/2021

User ID PohSuan

		42611-47140	WHEEL DISC. FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given	X
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
		43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given	X
		75851-47900	MOULDING BODY, RH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given	X
		87910-47330	MIRROR ASSY, RH	1.00	\$1,307.10	25.00	\$980.33	Replace	Replace	✓
		87931-47200	MIRROR GLASS RH	0.00	\$212.80	0.00	\$0.00	Replace	Not Given	X
		81730-52090	MIRROR LAMP RH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given	X
		879157-4010	COVER, OUTER MIRROR, RH	1.00	\$107.40	25.00	\$80.55	Replace	Replace	✓
<b>Total</b>					<b>\$8,197.35</b>		<b>\$1,228.59</b>			

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

	1,228.59	
	-20%	L/S \$1,700/-
	<u>982.87</u>	
+	200.00	
+	<u>510.00</u>	
	1,692.87	