

SK Automobile Pte. Ltd.  
 (Co Reg. No. 201500047H)  
 8 Kaki Bukit Ave 4 #08-45/46  
 Premier@Kaki Bukit S(415875)  
 Tel : 6789 5155 Fax : 6783 5155

TO : ERGO	DATE : 5-May-21
ATTENTION : MOTOR CLAIMS DEPARTMENT	JOB TYPE : T/P CLAIMS
ESTIMATE REPORT :	
<b>OWNER PARTICULAR</b>	
NAME : 1XXXXX007N	<b>VEHICLE DETAILS</b>
ADDRESS : <i>Xiao Chen</i>	VEHICLE NO. : SGU5446X
TEL. NO. :	MODEL / MAKE : TOYOTA WISH
	CHASSIS NO. : ZNE10-0351270
	<b>ACCIDENT DETAIL</b>
OWNER INSUANCE : NTUC	DATE : 3-May-21
POLICY NO. : 5090564421-03	TIME : 16:10HRS

QUOTATION SUMMARY PAGE 01  
 CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	REAR TAILGATE <i>Ryis</i>	1	\$ 1,273.90	\$ 1,273.90	X
2	REAR TAILGATE WINSCREEN MOULDING <i>Norm</i>	1	\$ 177.60	\$ 177.60	X.
3	REAR TAILGATE LOGO EMBLEM <i>Norm</i>	1	\$ 92.80	\$ 92.80	✓
4	REAR TAILGATE INNER TRIM BOARD <i>Norm</i>	1	\$ 486.10	\$ 486.10	X.
5	REAR TAILGATE RUBBER GUIDE STOPPER LH/RH <i>Norm</i>	2	\$ 38.20	\$ 76.40	X
6	REAR TAILGATE MECHANISM LOCK <i>Norm</i>	1	\$ 443.90	\$ 443.90	X.
7	REAR TAILGATE WEATHER STRIP <i>Norm</i>	1	\$ 398.80	\$ 398.80	X
8	REAR TAILLAMP LH/RH <i>RH cracked</i>	2	\$ 497.70	\$ 995.40	418.
9	REAR TAILLAMP INNER PANEL RH <i>Ryis</i>	1	\$ 345.90	\$ 345.90	X
10	REAR TAILLAMP LOWER BRACKET LH/RH <i>Norm</i>	2	\$ 28.50	\$ 57.00	X
11	REAR TAILLAMP BACK RUBBER GASKET LH/RH <i>RH NBSL</i>	2	\$ 19.40	\$ 38.80	19.40
12	REAR BUMPER <i>Deformed</i>	1	\$ 575.90	\$ 575.90	✓
13	REAR BUMPER REFLECTOR RH <i>Norm</i>	1	\$ 58.80	\$ 58.80	X
14	REAR BUMPER SIDE RETAINER LH/RH <i>RH Damaged</i>	2	\$ 75.60	\$ 151.20	75.60
15	REAR BUMPER SCREW WITH GARNISH LH/RH <i>Norm</i>	2	\$ 29.40	\$ 58.80	X
16	REAR BUMPER INNER SIDE SHIELD RH <i>3 NBS</i>	1	\$ 85.30	\$ 85.30	X
17	REAR WHEEL HOUSE PANEL ASSY RH <i>3 NBS</i>	1	\$ 456.80	\$ 456.80	X
18	REAR FENDER RH <i>Distorted</i>	1	\$ 950.90	\$ 950.90	✓
19	REAR FENDER GLASS WITH MOULDING RH <i>Norm</i>	1	\$ 467.80	\$ 467.80	60.
20	REAR FENDER INNER AIR VENT RH <i>Norm</i>	1	\$ 145.60	\$ 145.60	X
21	REAR FENDER INNER TRIM BOARD RH <i>3 NBS</i>	1	\$ 635.70	\$ 635.70	X
22	REAR FENDER INNER PANEL RH <i>1 m</i>	1	\$ 667.50	\$ 667.50	X
			TOTAL PRICE	\$ 8,640.90	
			LESS -25%	\$ (2,160.23)	
			<b>SUB TOTAL PRICE</b>	<b>\$ 6,480.68</b>	

*2192.60*  
*1644.45*

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR TAILGATE WINSCREEN SEALANT WITH PRIMER SET <i>2nd</i>	1	\$ 100.00	\$ 100.00	+
2	REAR TAILGATE WINSCREEN INNER GARNISH CLIPS SET <i>1st</i>	1	\$ 60.00	\$ 60.00	+
3	REAR TAILGATE SPOILER CLIPS SET <i>1st</i>	1	\$ 60.00	\$ 60.00	+
4	REAR TAILGATE OUTER CHROME GARNISH CLIPS SET <i>1st</i>	1	\$ 50.00	\$ 50.00	+
5	REAR TAILGATE INNER TRIM BOARD CLIPS SET <i>1st</i>	1	\$ 80.00	\$ 80.00	+
6	REAR TAILLAMP CLIPS SET LH/RH <i>1st</i>	2	\$ 50.00	\$ 100.00	20
7	REAR TAILLAMP INNER PANEL SEALANT RH <i>1st</i>	1	\$ 60.00	\$ 60.00	+
8	REAR BUMPER CLIPS SET <i>1st</i>	1	\$ 80.00	\$ 80.00	30
9	REAR WHEEL HOUSE PANEL SEALANT RH <i>1st</i>	1	\$ 60.00	\$ 60.00	+
10	REAR FENDER SEALANT RH <i>1st</i>	1	\$ 120.00	\$ 120.00	50
11	REAR FENDER GLASS SEALANT WITH PRIMER SET RH <i>1st</i>	1	\$ 80.00	\$ 80.00	40
12	REAR FENDER GLASS INNER GARNISH BACK CLIPS SET RH <i>1st</i>	1	\$ 50.00	\$ 50.00	+
13	REAR FENDER INNER TRIM BOARD CLIPS SET RH <i>1st</i>	1	\$ 80.00	\$ 80.00	+
14	REAR FENDER INNER PANEL SEALANT RH <i>1st</i>	1	\$ 50.00	\$ 50.00	+

TOTAL \$ 1,030.00

140

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS

REPAIR UNDER : PART BY PART OR LUMPSUM

DATE / TIME OF SURVEY :

SURVEYED BY / FROM :

CONTACT NUMBER :

FAX NUMBER :

EMAIL ADDRESS :

DATE / TIME OF RE-SURVEY :

EXCESS :

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,800.00	600.	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,400.00	800.	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 105.00	60.	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30.	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	\$ 150.00	X	
TO DISMANTLE & REINSTALL REAR FENDER GLASS RH PERFORM	\$ 120.00	50.	
TO PERFORM TRANSFER REAR TAILGATE MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	\$ 250.00	X	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	50	
TO DISMANTLE & REPLACED REAR INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 250.00	60.	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	X	

**TOTAL**                      \$                      4,315.00

1650

Adrian Ling.  
 x/s 06/05/21.  
 06 Pays.

total: 3434.45

L/s: 2.7K. ✓

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,510.68  
 TOTAL LABOUR COST : \$ 4,315.00  
 TOTAL REPAIR COST : \$ 11,825.68

**LKK Auto Consultants** heretofore  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_