

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Apr-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6975 L

1 pc	Boot lid	\$	1,119.00	XSVL
1 pc	Boot lid lock	\$	99.00	XSVL
1 pc	Bootlid lock cable	\$	35.00	XSVL
1 pc	Bootlid striker	\$	21.00	XSVL
1 pc	Bootlid emblem	\$	27.00	NBC
1 pc	Bootlid CRDi	\$	29.00	NBC
1 pc	Boot lid rubber weatherstrip	\$	96.00	XSVL
1 pc	Boot lid lower garnish	\$	290.00	XR
2 pcs	Bootlid hinges @ \$66.00	\$	132.00	X SVL
2 pcs	Rear license plate lamp @ \$30.00	\$	60.00	XSVL
2 pcs	Bootlid hinge torsion bar @ \$33.00	\$	66.00	XSVL
1 pc	Handle trunk lid hook	\$	5.00	XNW
1 pc	Bootlid inner trim	\$	190.00	?
1 pc	End panel	\$	250.00	?
1 pc	End panel inner garnish	\$	74.00	?
1 pc	Rear bumper	\$	696.00	DEF
1 pc	Rear bumper lower cover	\$	206.00	DEF
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	?
1 pc	Rear bumper inner sponge	\$	114.00	?
1 pc	Rear bumper reinforcement	\$	607.00	?
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00	?
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	?
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	?
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00	XSVL
		\$	4,446.00	
		Less 10%	\$	444.60
			\$	4,001.40

20-Apr-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6975 L

S/NETT

1 set	Rear bumper clips		\$	48.00	/ NRE
1 set	End panel inner garnish clips		\$	30.00	?
1 set	Bootlid inner trim clips		\$	52.00	?
1 set	Bootlid lower garnish clips		\$	60.00	X SUC
1 set	Bootlid stickers	30	\$	100.00	NRE
1 set	Reverse sensor		\$	280.00	X SUC
1 pc	Rear bumper top protector	50	\$	80.00	NRE
1 pc	Rear no. plate with casing		\$	50.00	X SUC
1 pc	Sealant		\$	50.00	?
	Sundry		\$	50.00	NN
	To dismantle / replace reverse sensor to new bumper and reset to the same		\$	120.00	30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00	?
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel, rear n/s & o/s fenders. Including knock-out, straighten, repair, reshape and adjust of the rear panel			\$1,000.00	360
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, bootfloor		\$	1,000.00	280
	To apply rustproofing on the repaired and replaced panels.		\$	120.00	40
			\$	<u>7,221.40</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NAZ LKK
 10/5/2021 1645
 LIS
 3 DAYS
 CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS