

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TPSMRT
Hui Zhen

KOH HUI KEOW
BLK 162 JALAN TECK WHYE #14-204
SINGAPORE 680162

ESTIMATE

Repair Code : CLM16797

Date in : 06/05/2021

Vehicle Num. : SLL9099B

Model : TOYOTA HARRIER M GRADE

Chassis/Eng# : JTEZB3GH00J005784/8ARZ204673

Contact : 94877828

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR SIDE MIRROR <i>Damaged</i>	1	1548.80	<i>1303</i> 1,548.80
FRONT RH DOOR SIDE MIRROR COVER <i>Missing</i>	1	102.60	✓ 102.60
REAR BUMPER <i>Deformed</i>	1	1453.00	<i>792</i> 1,453.00
REAR BUMPER LOWER LID GARNISH <i>Cut</i>	1	466.00	✓ 466.00
REAR BUMPER RH END SEAL COVER <i>Not nee</i>	2	82.00	X 164.00
REAR BUMPER SIDE RETAINER L/R <i>RH Damaged</i>	2 <i>4479.4</i>	82.70	<i>82.70</i> 165.40
REAR RH DOOR <i>Repair</i>	1	1550.40	X 1,550.40
REAR RH DOOR INNER PLASTIC SEAL COVER <i>Not nee</i>	1 <i>335555</i>	36.60	X 36.60
REAR RH DOOR VERTICAL GARNISH <i>Not nee</i>	1 <i>5N.1400</i>	96.00	X 96.00
REAR RH FENDER <i>Distorted</i>	1 <i>403.40</i>	1531.10	✓ 1,531.10
REAR RH FENDER INNER SHIELD <i>Not nee</i>	1 <i>300.05</i>	169.80	X 169.80
REAR RH FENDER QUARTER GLASS MOULDING <i>Not nee</i>	1 <i>700 (SW)</i>	202.00	✓ 202.00
REAR RH SPORT RIM <i>Cut</i>	1	2604.90	<i>1400 (SW)</i> 2,604.90 <i>700 (SW)</i>
REAR RH TAILLAMP LOWER BRACKET <i>Not nee</i>	1	121.20	X 121.20
Subtotal before discount			10,211.80
Percentage discount 25%			2,552.95
Sub-total 1			7,658.85
DOOR VISOR GARNISH - SET <i>Not nee</i>	1	250.00	X 250.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KOH HUI KEOW
BLK 162 JALAN TECK WHYE #14-204
SINGAPORE 680162

Contact : 94877828

ESTIMATE

Repair Code : CLM16797

Date in : 06/05/2021

Vehicle Num. : SLL9099B

Model : TOYOTA HARRIER M GRADE

Chassis/Eng# : JTEZB3GH00J005784/8ARZ204673

REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	<i>30</i> 50.00
REAR BUMPER RH END SEAL COVER CLIPS - SET	1	30.00	<i>+</i> 30.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	<i>+</i> 50.00
REAR RH FENDER INNER SHIELD CLIPS - SET	1	30.00	<i>+</i> 30.00
REAR RH FENDER QUARTER GLASS SEALANT <i>new</i>	1	60.00	<i>40</i> 60.00
REAR RH TYRE <i>lit</i>	1	480.00	<i>+</i> 480.00 <i>280</i>
Subtotal before discount			950.00
Percentage discount 0%			0.00
Sub-total 2			950.00
Parts-total			8,608.85

LABOUR

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall fender glass

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

3,350.00

11,958.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*** This is a computer-generated document which requires no signature.***

page 2

total: 7255.55
2/5: 58K.
06 Days.

(5.81C)