

Repair Estimate

*Not authorized
1/1mp & 420dp*

Fulco Autocare Pte Ltd

*After Paint
3 days*

176 Sin Ming Drive #03-02 Sin Ming Autocare Singapore 575721

Tel: (65) 6552 0302 Fax: (65) 6552 0780 Email: admin@fulcoautocare.com

Make/Model: TOYOTA ALTIS-HYBRID
Engine/Chassis No.: JTNK93BE603003424
Date of accident:
Damaged area: Front

Date: 05/05/2021
Claim Type: TP
VRN: SMS8048G



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Bonnet	<i>R</i> 1	\$ 1,783.00	\$ 1,783.00	X
2	Bonnet lock	<i>R</i> 1	\$ 339.00	\$ 339.00	X
3	Bonnet bottom lock assy	<i>R</i> 1	\$ 158.00	\$ 158.00	X
4	Support panel	<i>R</i> 1	\$ 835.00	\$ 835.00	X
5	Support panel top garnish	<i>R</i> 1	\$ 298.00	\$ 298.00	X
6	Headlamp support	<i>R</i> 2	\$ 167.00	\$ 334.00	X
7	Headlamp	<i>mg cmf</i> 2	\$ 2,896.00	\$ 5,792.00	X
8	Headlamp lower bracket	<i>R</i> 2	\$ 78.00	\$ 156.00	X
9	Front bumper <i>3H-30</i>	<i>bu / mg</i> 1 <i>cmf</i>	\$ 1,586.00	\$ 1,586.00	X
10	Front bumper side chrome moulding	<i>su</i> 2	\$ 375.00	\$ 750.00	X
11	Radiator grille "TOYOTA" logo	<i>su</i> 1	\$ 116.00	\$ 116.00	X
12	Front bumper side retainer	<i>su</i> 2	\$ 88.00	\$ 176.00	X
13	Front bumper bracket	<i>R</i> 2	\$ 54.00	\$ 108.00	X
14	Radiator grille <i>312-50</i>	<i>cmf</i> 1	\$ 657.00	\$ 657.00	X
15	Front bumper sponge	<i>su</i> 1	\$ 278.00	\$ 278.00	X
16	Front bumper lower grille	<i>su</i> 1	\$ 594.00	\$ 594.00	X
17	Front bumper reinforcement	<i>R</i> 1	\$ 689.00	\$ 689.00	X
Subtotal				\$ 14,649.00	
List discount				25.00%	
Total				\$ 10,986.75	

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Bonnet insulator clips	<i>na</i> 12	\$ 5.50	\$ 66.00	X
2	Radiator coolant	<i>na</i> 1	\$ 80.00	\$ 80.00	X
3	Front bumper clips	<i>na</i> 12	\$ 5.50	\$ 66.00	X
4	Sundries	<i>na</i> 1	\$ 50.00	\$ 50.00	X
Total				\$ 262.00	

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,550.00
Estimate Grand Total			\$ 13,798.75

300h
20h
400h
x

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: