

Tanjore

Q3/ASM 21005558/T19C

## ASSIGNMENT

Instruction

Repairs Range \$5000-\$6000, 7 days

The U/C / Chassis frame / Body Structure affected due to collision.

7574

1