

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD CS3/ASM21005558/T1qce2 Ref: 8 SHENTON WAY #24-01 AXA Date: 23/06/2021 **TOWERSINGAPORE 068811** ATTN: KHOR SAW THENG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. GBE 9696H **SHC 3212A** Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M039IQ Excess (\$) 0.00 KHOR SAW THENG **Assign Date** 06/05/2021 Assign From **Vehicle Particulars & Condition** 2. TOYOTA HIACE c.c Make & Model 2982 2015 HIDDEN Year of Reg. Engine No. JTFHT02P500162184 SILVER Chassis No. Colour Odometer 80105 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15 CST 6 mm CST L/H Front Tyre 195 R15 6 mm 195 R15 CST R/H Rear Tyre 6 mm CST L/H Rear Tyre 195 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 04/05/2021 06/05/2021 (12:19 PM) Inspect Date / Time Accident Date **GARAGE 13 PTE LTD** Survey held at 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

Remarks

5b. **Estimate Days of Repair** 

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 7 Working Days

Report Ref No. CS3/ASM21005558/T1qce2

Inspected By

5a.

**MOHAMAD TAUFIKH** 

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

**Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.