



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21003407/T1vf3e2-1	
			Date: 07/06/2021	
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	YN 8327K	Veh. Inspected	SJJ 9360E
	Policy No.		Coverage (\$)	0.00
	Claim No.	20/21/21/VC00/024327	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	06/05/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA FIT	c.c	1339
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	GE61107654	Colour	WHITE
	Odometer	206454 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	WEST LAKE	6 mm
	L/H Front Tyre	195/55 R15	WEST LAKE	6 mm
	R/H Rear Tyre	195/55 R15	WEST LAKE	6 mm
	L/H Rear Tyre	195/55 R15	WEST LAKE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	15/03/2021	Inspection Date	16/03/2021
	Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	