

PLEASE ARRANGE TO SURVEY  
VEHICLE AT 30 BUKIT BATOK  
CRESCENT (S 658075)

Selamatshahh  
CLAIM DEPARTMENT  
DID : 66547519  
FAX :

Date : 06/05/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD  
**ESTIMATION**

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTHCVE000218 Accident Date : 01/05/2021

Vehicle No : GBJ-9147-A Make & Model : ISUZU NHR87AUE4AA 1.9 G (M) EURO 6

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	FRONT BUMPER <i>de</i>	1,434.00	/
1	FRONT BUMPER BRACKET RH <i>bt</i>	298.00	/
1	HEADLAMP RH <i>cm</i>	1,344.00	/
1	SIDE LAMP RH <i>cm</i>	362.00	/
1	FRONT DOOR RH	RESTORE	
1	FRONT CORNER PANEL RH	RESTORE	
	Sub Total	3438.00	
	Discount 15% On Parts	(515.70)	
<u>Special Nett Item</u>			
1	FRONT DOOR ADVERTISEMENT <i>nm</i>	150.00	/

3438  
1576  
2922.30

P-2922.30  
 s/w- 1701.00  
 L- 630.00  
 93.50  
 15%  
 79.47  
 Supp'l - 79.47  
 3801.77 = 3801.78

**ETHOZ**

Date : 06/05/2021

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**  
**ESTIMATION**

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTHCVE000218

Accident Date : 01/05/2021

Vehicle No : GBJ-9147-A

Make & Model : ISUZU NHR87AUE4AA 1.9 G (M) EURO 6

**ESTIMATED REPAIR COST DETAILS**

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	ROC STICKER <i>see</i>	20.00	
	Sub Total	170.00	<i>170</i>
<b>Labour &amp; Misc</b>			
	LABOUR TO FACILITATE REPAIR	600.00	<i>300</i>
	TO RESPRAY AFFECTED AREAS	600.00	<i>300</i>
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	<i>630</i>
	Sub Total	1230.00	
		4,322.30	

Remarks:

*4 days / part by part / Repair before print*

SUB TOTAL

GST 7.0 % 302.56

TOTAL 4,624.86

Surveyor's name: *RASUL - Hp 90010068*

Principal's name: ETHOZ Group Ltd

Survey Date & Time: *06/05/21 @ 1535*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

PAGE :

Signature:

Date:

Selamatshahh  
CLAIM DEPARTMENT  
DID : 66547519  
FAX :

Date : 21/05/2021

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**  
**SUPPLEMENTARY**

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTHCVE000218 Accident Date : 01/05/2021

Vehicle No : GBJ-9147-A Make & Model : ISUZU NHR87AUE4AA 1.9 G (M) EURO 6

**ESTIMATED REPAIR COST DETAILS**

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<b>List Item</b>			
1	FRONT DOOR STICKER RH <b>NEC</b> ✓	93.50	
	<b>Sub Total</b>	<b>93.50</b>	
	<b>Discount 15% On Parts</b>	<b>(14.03)</b>	

79.47

Remarks:

**SUB TOTAL**

**GST 7.0 %** 5.56

**TOTAL** 85.04

Surveyor's name: \_\_\_\_\_