

SERVICE ESTIMATE

93325 - C00001 SL: SERVICE SALES - PC
 Mr Mendonca Tolentino Manoj
 21 Jalan Raja Udang
 #14-01
 The Arte
 Singapore 329215

GST Reg.No: M28920628X
 Inv.No. . . : B&P 0 Page 1
 Inv.date. . : 10/05/2021
 WIP No. . . : 23192
 Veh.In/Out: 04/05/2021
 *Tel.No. . . : Mobile: 96150203
 Reg.No. . . : SLR8417S
 Reg.date . . : 29/08/2017
 Mileage . . . : 0
 Chassis No: SALCA2AN5HH715989

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : Mr Mendonca Tolentin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE TAILGATE, REAR BUMPER, REAR WHEEL HOUSE RH, TAIL LAMP RH, REPAIR REAR DOOR LH, ETC	0	8000.00	0		8,000.00 S	
						7500	
800	TO SPRAY TAILGATE, REAR BUMPER, REAR FENDER LH, REAR WHEEL HOUSE LH, REAR DOOR LH.	0	6000.00	0		6,000.00 S	
						5000	
802	TO REMOVE, REFIT & TRANSFER TAILGATE INTERIOR COMPONENTS	0	500.00	0		500.00 S	
802	TO REMOVE AND REFIT INTERIOR TRIM, FITTING, CARPET, ETC	0	2000.00	0		2,000.00 S	
						1600	
802	TO REPLACE REAR WINDSCREEN	0	1200.00	0		1,200.00 S	
0080	TO INSTALL REAR WINDSCREEN FILM	0	280.00	0		280.00 S	
0031	TO REPLACE FRONT & REAR RIM RH	0	100.00	0		100.00 S	
0031	TO REPLACE FRONT & REAR TYRE R	0	1500.00	0		1,500.00 S	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 9601w 68
15 days
10/05/21 @ 1145
Resy before print

SERVICE ESTIMATE

93325 - C00001 SL: SERVICE SALES - PC

Mr Mendonca Tolentino Manoj
21 Jalan Raja Udang
#14-01
The Arte
Singapore 329215

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 2
Inv.date. : 10/05/2021
WIP No. . : 23192
Veh.In/Out: 04/05/2021
*Tel.No. . : Mobile: 96150203
Reg.No. . : SLR8417S
Reg.date. : 29/08/2017
Mileage . : 0
Chassis No: SALCA2AN5HH715989

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Mendonca Tolentin

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
419	WHEEL ALIGNMENT	0		280.00	0		280.00	S
287	TO REPLACE FRONT & REAR	0		6624.00	0		6,624.00	S
SUSPENSION						3312		
280	TO CHECK WIRING INCLUDE	0		621.00	0		621.00	S
RESETTING OF ALL ELECTRICAL								
MODULES								
287	TO REPLACE AIRBAG COMPONENT,	0		3312.00	0		3,312.00	S
ETC								
	DISC - BRAKE - VENTE	2.0	EA	413.00			826.00	S
	BRAKE PADS - LESS SP	1.0	EA	611.20			611.20	S
	WIRE - BRAKE PAD WEA	1.0	EA	96.40			96.40	S
	BRAKE DISC REAR DSPO	2.0	EA	317.90			635.80	S
	BRAKE PAD REAR DSPOR	1.0	EA	404.50			404.50	S
	WIRE - BRAKE PAD WEA	1.0	EA	93.60			93.60	S
	D BRAKE CLEANER 50	2.0	EA	10.00			20.00	S
	HOSE - BRAKE RH FRON	1.0	EA	189.90			189.90	S
	HOSE - BRAKE RH REAR	1.0	EA	91.80			91.80	S

SERVICE ESTIMATE

93325 - C00001 SL: SERVICE SALES - PC

Mr Mendonca Tolentino Manoj

21 Jalan Raja Udang

#14-01

The Arte

Singapore 329215

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3

Inv.date. : 10/05/2021

WIP No. . : 23192

Veh.In/Out: 04/05/2021

*Tel.No. . : Mobile: 96150203

Reg.No. . : SLR8417S

Reg.date. : 29/08/2017

Mileage . : 0

Chassis No: SALCA2AN5HH715989

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Mr Mendonca Tolentin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BRAKE FLUID 0.5L DOT <i>ne</i>	4.0 EA	34.70			138.80	S
	LEVEL SENSOR FRT EVO <i>cm</i>	1.0 EA	325.60			325.60	S
	SHIELD - BRAKE DISC <i>bt</i>	1.0 EA	91.40			91.40	S
	BOLT <i>ne</i>	2.0 EA	11.00			22.00	S
	BRAKE DISC SCREW FL2 <i>ne</i>	2.0 EA	7.80			15.60	S
	ARM - LOWER FRONT SU <i>bt</i>	1.0 EA	800.10			800.10	S
	BOLT M14X85 EVOQUE <i>ne</i>	2.0 EA	16.10			32.20	S
	SUSPENSION NUT M14 <i>ne</i>	2.0 EA	4.70			9.40	S
	BOLT M14X90 EVOQUE <i>ne</i>	1.0 EA	10.20			10.20	S
	BOLT <i>ne</i>	1.0 EA	8.80			8.80	S
	NUT M12X1.75MM DIS4 <i>ne</i>	1.0 EA	4.70			4.70	S
	SHAFT - FRONT AXLE <i>bt</i>	1.0 EA	1627.20			1,627.20	S
	DRIVESHAFT NUT M24X2 <i>ne</i>	1.0 EA	26.80			26.80	S
	KNUCKLE - FRONT WHEEL <i>bt</i>	1.0 EA	1385.70			1,385.70	S
	STABILIZER LINK FRT <i>bt</i>	1.0 EA	116.00			116.00	S
	NUT M10 EVOQUE <i>ne</i>	2.0 EA	4.50			9.00	S
	MACPHERSON STRUT	1.0 EA	685.70			685.70	S



SERVICE ESTIMATE

93325 - C00001 SL: SERVICE SALES - PC

Mr Mendonca Tolentino Manoj

21 Jalan Raja Udang

#14-01

The Arte

Singapore 329215

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 4

Inv.date. : 10/05/2021

WIP No. . : 23192

Veh. In/Out: 04/05/2021

*Tel.No. . : Mobile: 96150203

Reg.No. : SLR8417S

Reg.date. : 29/08/2017

Mileage . : 0

Chassis No: SALCA2AN5HH715989

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Mr Mendonca Tolentin

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	------	-----	-------	-------	-----	--------	---

ABSORBER MTG FRT EVO	1.0	EA	161.30	161.30	S
SPRING - SUSPENSION	1.0	EA	388.30	388.30	S
LLR121039/ABSORBER I	1.0	EA	116.50	116.50	S
ABSORBER BUMP STOP F	1.0	EA	33.90	33.90	S
ABSORBER BOOT FL2 EV	1.0	EA	79.40	79.40	S
ABSORBER PAD UPPER 1	1.0	EA	12.10	12.10	S
ABSORBER PAD LOWER E	1.0	EA	25.80	25.80	S
BOLT M8X17 EVOQUE	3.0	EA	2.90	8.70	S
BOLT M12X80 EVOQUE	1.0	EA	9.50	9.50	S
NUT	1.0	EA	8.40	8.40	S
CROSS MEMBER - FRONT	1.0	EA	2390.40	2,390.40	S
SUBFRAME BOLT M16 EV	4.0	EA	27.40	109.60	S
SUPPORT - ENGINE MOU	1.0	EA	825.40	825.40	S
ENG MTG LOWER FL2 2.	1.0	EA	197.10	197.10	S
BOLT - HEX.HEAD 7.	2.0	EA	6.50	13.00	S
SCREW	1.0	EA	11.90	11.90	S
BOLT	1.0	EA	9.90	9.90	S

SERVICE ESTIMATE

93325 - C00001 SL: SERVICE SALES - PC

Mr Mendonca Tolentino Manoj
21 Jalan Raja Udang
#14-01
The Arte
Singapore 329215

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 5
Inv.date. : 10/05/2021
WIP No. . : 23192
Veh.In/Out: 04/05/2021
*Tel.No. . : Mobile: 96150203
Reg.No. . : SLR8417S
Reg.date. : 29/08/2017
Mileage . : 0
Chassis No: SALCA2AN5HH715989

Closed by : Juan Paulo Bongon Ba
Svc Consultant :
Remarks : Mr Mendonca Tolentin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	SENSOR - TRIPMINDER?	1.0 EA	405.10			405.10	S
	ARM - REAR SUSPENSIO <i>ca</i>	1.0 EA	771.60			771.60	S
	BOLT - FLANGED HEX. <i>ne</i>	3.0 EA	19.60			58.80	S
	NUT - FLAG TYPE <i>ne</i>	1.0 EA	29.20			29.20	S
	ARM - REAR SUSPENSIO <i>bt</i>	1.0 EA	381.30			381.30	S
	BOLT <i>ne</i>	1.0 EA	36.20			36.20	S
	SUSPENSION NUT M14 F <i>ne</i>	1.0 EA	4.70			4.70	S
	WASHER - ADJUSTING <i>ne</i>	1.0 EA	13.10			13.10	S
	BOLT - FLANGED HEX. <i>ne</i>	1.0 EA	13.90			13.90	S
	NUT <i>ne</i>	1.0 EA	8.40			8.40	S
	ARM - REAR SUSPENSIO <i>bt</i>	1.0 EA	371.20			371.20	S
	BOLT - FLANGED HEX <i>ne</i>	2.0 EA	14.10			28.20	S
	NUT <i>ne</i>	2.0 EA	8.40			16.80	S
	SHOCK ABSORBER - REA <i>bt</i>	1.0 EA	635.80			635.80	S
	BRACKET - SHOCK ABSO <i>ne</i>	1.0 EA	132.10			132.10	S
	BOOT - SHOCK ABSORBE <i>ne</i>	1.0 EA	80.50			80.50	S
	NUT <i>ne</i>	2.0 EA	8.40			16.80	S

SERVICE ESTIMATE

93325 - C00001 SL: SERVICE SALES - PC

Mr Mendonca Tolentino Manoj

21 Jalan Raja Udang

#14-01

The Arte

Singapore 329215

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 6

Inv.date. : 10/05/2021

WIP No. . : 23192

Veh.In/Out: 04/05/2021

*Tel.No. . : Mobile: 96150203

Reg.No. . : SLR8417S

Reg.date. : 29/08/2017

Mileage . : 0

Chassis No: SALCA2AN5HH715989

Closed by . . . : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Mr Mendonca Tolentin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BOLT <i>re/</i>	1.0 EA	29.10			29.10	S
	NUT <i>re/</i>	1.0 EA	10.80			10.80	S
	KIT - SUSPENSION SPR <i>re/</i>	1.0 EA	311.20			311.20	S
	KNUCKLE - REAR WHEEL <i>bt/</i>	1.0 EA	993.60			993.60	S
	BEARING - WHEEL HUB <i>re/</i>	1.0 EA	357.40			357.40	S
	JOINT AND STUB SHAFT <i>?</i>	1.0 EA	1754.40			1,754.40	S
	DRIVESHAFT NUT M24X2 <i>bt/</i>	1.0 EA	26.80			26.80	S
	DIFFERENTIAL AND CAR <i>?</i>	1.0 EA	6299.40			6,299.40	S
	DRIVE SHAFT COUPLING <i>?</i>	1.0 EA	9727.20			9,727.20	S
	SHIELD - BRAKE DISC <i>bt/</i>	1.0 EA	206.60			206.60	S
	SCREW <i>re/</i>	3.0 EA	1.90			5.70	S
	HUB - WHEEL <i>bt/</i>	1.0 EA	826.70			826.70	S
	WHEEL BEARING CLIP E <i>re/</i>	1.0 EA	21.00			21.00	S
	LINK - STABILIZER BA <i>bt/</i>	1.0 EA	133.00			133.00	S
	STABILIZER LINK NUT <i>re/</i>	2.0 EA	12.30			24.60	S
	BAR - REAR STABILIZE <i>bt/</i>	1.0 EA	312.50			312.50	S
	INSULATOR - STABILIZ <i>re/</i>	2.0 EA	95.80			191.60	S



93325 - C00001 SL: SERVICE SALES - PC

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 7

Inv.date. : 10/05/2021

WIP No. . : 23192

Veh. In/Out: 04/05/2021

*Tel.No. : Mobile: 96150203

Reg.No. . : SLR8417S

Reg.date. : 29/08/2017

Mileage . : 0

Chassis No: SALCA2AN5HH715989

Svc Consultant :

Remarks : Mr Mendonca Tolentin

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
	PIPE - FUEL FILLER?		1.0 EA	425.40			425.40	S
	CAP-FUEL FILLER <i>mis</i>		1.0 EA	74.20			74.20	S
	CROSSMEMBER - REAR <i>bf</i>		1.0 EA	4028.50			4,028.50	S
	BOLT - FLANGED HEX <i>ne</i>		4.0 EA	30.20			120.80	S
	SENSOR - ABS?		1.0 EA	326.40			326.40	S
	LINK - SUSPENSION AR?		2.0 EA	26.80			53.60	S
	SENSOR - AIR SUSPENS?		1.0 EA	325.60			325.60	S
	LAMP - REAR- STOP AN <i>ca</i>		1.0 EA	720.20			720.20	S
	AIR BAG - CURTAIN <i>ms</i>		1.0 EA	1161.00			1,161.00	S
	E SIDE AIR BAG <i>ms</i>		1.0 EA	1098.70			1,098.70	S
	COVER - FRONT SEAT <i>Turn</i>		1.0 EA	2393.70			2,393.70	S
	PAD - SEAT BACK <i>ne</i>		1.0 EA	409.40			409.40	S
	HEADLINING - ROOF <i>de</i>		1.0 EA	3603.10			3,603.10	S
	BUCKLE - SEAT BELT <i>X NN</i>		1.0 EA	230.30			230.30	S
	E SEAT BELT AND RE <i>X NN</i>		1.0 EA	814.70			814.70	S
	MONITOR - AIRBAG DIA <i>ms</i>		1.0 EA	1884.60			1,884.60	S
	PANEL - BODY SIDE - <i>sm</i>		1.0 EA	3218.30			3,218.30	S

SERVICE ESTIMATE

93325 - C00001 SL: SERVICE SALES - PC

Mr Mendonca Tolentino Manoj

21 Jalan Raja Udang

#14-01

The Arte

Singapore 329215

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 9

Inv.date. : 10/05/2021

WIP No. : 23192

Veh.In/Out: 04/05/2021

*Tel.No. : Mobile: 96150203

Reg.No. : SLR8417S

Reg.date. : 29/08/2017

Mileage : 0

Chassis No: SALCA2AN5HH715989

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Mr Mendonca Tolentin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	AIR VENT REAR FL2 DI?	1.0 EA	119.60			119.60	S
	MUFFLER - REAR RH <i>bt</i>	1.0 EA	2447.20			2,447.20	S
	MUFFLER - REAR LH <i>X NN</i>	1.0 EA	2492.70			2,492.70	S
	SHIELD - FLOOR RH	1.0 EA	236.80			236.80	S
	SHIELD - REAR FLOOR ?	1.0 EA	77.60			77.60	S
	ALLOY WHEEL STYLE 52 <i>at</i>	2.0 EA	1368.80			2,737.60	S
	D PILLAR FINISHER RH <i>ca</i>	1.0 EA	109.10			109.10	S
	PANEL - WHEELHOUSE - <i>Takw</i>	1.0 EA	1099.70			1,099.70	S
	PANEL - REAR LAMP CL <i>X NN</i>	1.0 EA	394.90			394.90	S
	PANEL - REAR LAMP CL <i>X NN</i>	1.0 EA	273.50			273.50	S
	DOOR - FUEL TANK FIL <i>X NN</i>	1.0 EA	218.40			218.40	S
	HOUSING - FUEL TANK	1.0 EA	317.20			317.20	S
	GASKET - FILLER PIPE <i>re</i>	1.0 EA	68.60			68.60	S
	LLR073071/BUMPER - R <i>de</i>	1.0 EA	1774.40			1,774.40	S
	BRACKET - BUMPER MOU <i>re</i>	1.0 EA	124.60			124.60	S
	BUMPER - COVER LOWER <i>sen</i>	1.0 EA	574.10			574.10	S
	TOW HOOK COVER REAR <i>mis</i>	1.0 EA	29.60			29.60	S

SERVICE ESTIMATE

93325 - C00001 SL: SERVICE SALES - PC

Mr Mendonca Tolentino Manoj

21 Jalan Raja Udang

#14-01

The Arte

Singapore 329215

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 8

Inv.date. : 10/05/2021

WIP No. . : 23192

Veh.In/Out: 04/05/2021

*Tel.No. . : Mobile: 96150203

Reg.No. . : SLR8417S

Reg.date. : 29/08/2017

Mileage . : 0

Chassis No: SALCA2AN5HH715989

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Mr Mendonca Tolentin

Op.No	Description	Mech Qty	Price Disc%	Pkg Amount G
	GLASS - QUARTER WIND <i>bro</i>	1.0 EA	605.60	605.60 S
	JC2D7026/SEALANT WIN <i>na</i>	4.0 EA	159.50	638.00 S
	D PRIMER GLASS & P <i>na</i>	2.0 EA	43.30	86.60 S
	GLASS - BACK WINDOW <i>?</i>	1.0 EA	1123.30	1,123.30 S
	TAILGATE PANEL DSPOR <i>bt</i>	1.0 EA	3548.90	3,548.90 S
	BADGE REAR "DISCO" D <i>na</i>	1.0 EA	171.90	171.90 S
	BADGE REAR "VERY" DS <i>na</i>	1.0 EA	154.20	154.20 S
	BADGE OVAL REAR RR3 <i>na</i>	1.0 EA	91.50	91.50 S
	LAMP - REAR- STOP AN <i>X NN</i>	1.0 EA	720.20	720.20 S
	LAMP - FOG - REAR RH <i>ca</i>	1.0 EA	364.50	364.50 S
	TAILLAMP RH <i>ca</i>	1.0 EA	652.40	652.40 S
	MOULDING - TAILGATE <i>na</i>	1.0 EA	1355.20	1,355.20 S
	COVER - HINGE RH <i>X NN</i>	1.0 EA	44.90	44.90 S
	SHIELD - SPLASH - WH <i>na</i>	1.0 EA	437.80	437.80 S
	FUEL FILLER CAP RRS2 <i>?</i>	1.0 EA	83.70	83.70 S
	MOULDING - REAR WHEE <i>na</i>	1.0 EA	321.80	321.80 S
	LLR058529/MOULDING A <i>?</i>	1.0 EA	201.90	201.90 S

SERVICE ESTIMATE

93325 - C00001 SL: SERVICE SALES - PC

Mr Mendonca Tolentino Manoj

21 Jalan Raja Udang

#14-01

The Arte

Singapore 329215

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 10

Inv.date. : 10/05/2021

WIP No. . : 23192

Veh.In/Out: 04/05/2021

*Tel.No. . : Mobile: 96150203

Reg.No. . : SLR8417S

Reg.date. : 29/08/2017

Mileage . : 0

Chassis No: SALCA2AN5HH715989

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Mr Mendonca Tolentin

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BRACKET - BUMPER RH <i>Ne</i>	1.0 EA	188.10			188.10	S
	LLR059014/REINFORCEM <i>?</i>	1.0 EA	650.40			650.40	S
	SENSOR - PARKING AID <i>scu</i>	<i>1pc</i> 4.0 EA	389.00			1,556.00	S
	NAME PLATE <i>XNN</i>	1.0 EA	84.20			84.20	S
	HEATER & EVAPORATOR <i>?</i>	1.0 EA	2591.20			2,591.20	S
	BODY PANEL SEALANT <i>X</i>	1.0 EA	955.20			955.20	S
	ADHESIVE SEALER FL2 <i>scu</i>	1.0 EA	709.60			709.60	S
	3M07333 IMPACT RESIS <i>scu</i>	1.0 EA	84.10			84.10	S
	3M08115 PANEL BONDIN <i>scu</i>	1.0 EA	68.30			68.30	S
	D WELDING PRIMER <i>scu</i>	1.0 EA	74.90			74.90	S
	SOUND DEADENING PAD <i>scu XNN</i>	2.0 EA	578.00			1,156.00	S

Gross Total. 120,036.40

Net..... 120,036.40

GST @ 7.0% 8,402.55

Total..... 128,438.95

Paid..... 0.00

Please Pay.. 128,438.95

Labour Total 30,417.00
 Parts Total 89,619.40
 Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated