

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21005565/R1BS3Q2
Date: 27/07/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd
Claimant Vehicle No : SJN3668L
 Date of Loss: 26/04/2021

Policy No:
Insured Vehicle No : SLG5718B
 Nature of Claim: TP
 Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN3668L**
 Make & Model: TOYOTA COROLLA ALTIS, 1.8 (A)
 Reg. Date: 12/02/2009 (Man. Year: 2009)
 Colour: White
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 3ZZ4862964
 Chassis No: MR053ZEE106139810
 Odometer: 162443 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16
 Front Left Side: Michelin 5 mm
 Front Right Side: Michelin 5 mm

Rear Tyre Size: 205/55 R16
 Rear Left Side: Michelin 5 mm
 Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,158.52	1,045.68	112.84	9.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,765.00	1,020.00	745.00	42.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,923.52	2,065.68	857.84	29.34
Approved Total (Overridden) (S\$)		1,650.00		

(S\$)	2,923.52	1,650.00	1,273.52	43.56
+ GST 7.00/7.00% (S\$)	204.65	115.50	89.15	43.56
Nett Amount (S\$)	3,128.17	1,765.50	1,362.67	43.56
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 06/05/2021

Date Inspected: 10/05/2021

Estimated Period of Repair: 4.0 days

Inspected At: Ethoz Group Ltd (HQ)
30 Bukit Batok Crescent
Singapore 658075

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN3668L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Bent	974.56 FL	*974.56 FL
2	1		*REAR DOOR HINGE LH (UPPER)	Serviceable	75.23 FL	*- FL
3	1		*REAR DOOR HINGE LH (LOWER)	Serviceable	75.23 FL	*- FL
4	1		*REAR DOOR STICKER LH (SET) (BLACK)	Necessary	85.44 FL	*85.44 FL
5	1		*REAR DOOR PROTECTOR LH	Necessary	134.24 FL	*134.24 FL
6	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
7	1		*ROCKER PANEL GARNISH LH (NPA)	Repair	0.00 FL	*- FL
8	1		*REPAIR -REAR SPORT RIM LH	Scratched	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,494.70	1,344.24
- List Item Discount on L Items 25.00/25.00% (S\$)	336.18	298.56
Total Parts (S\$)	1,158.52	1,045.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO CARRY OUT REAR REPAIR	New	700.00	400.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	35.00	0.00
3	TO SPRAY PAINTING ON AFFECTED AREAS	New	800.00	500.00
4	SPRAY RUST PROOF ON AFFECTED AREA	New	30.00	0.00
5	TO TRANSFER REAR DOOR LH FITTING	New	100.00	60.00
6	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	New	100.00	60.00
Gross Labour Cost (S\$)			1,765.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >