

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 04/05/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ABDUL RAHMAN BIN HASBIALLAH

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10298091R01

Accident Date : 26/04/2021

Vehicle No : SJN-3668-L

Make & Model : TOYOTA COROLLA ALTIS 1.6 (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	REAR DOOR LH <i>bt</i>	974.56	
1	REAR DOOR HINGE LH (UPPER) <i>X</i>	75.23	
1	REAR DOOR HINGE LH (LOWER) <i>X</i>	75.23	
1	REAR DOOR STICKER LH (SET)(BLACK) <i>re</i>	85.44	
1	REAR DOOR PROTECTOR LH <i>re</i>	134.24	
1	REAR FENDER LH <i>repair</i>	RESTORE	
1	ROCKER PANEL GARNISH LH <i>repair</i>	RESTORE	

Date : 04/05/2021

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ABDUL RAHMAN BIN HASBIALLAH

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10298091R01

Accident Date : 26/04/2021

Vehicle No : SJN-3668-L

Make & Model : TOYOTA COROLLA ALTIS 1.6 (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1344.70	
	Discount 25% On Parts	(336.18)	
	<u>Special Nett Item</u>		
1	REPAIR - REAR SPORT RIM LH <i>scr</i>	150.00	
	Sub Total	150.00	
	<u>Labour & Misc</u>		
	LABOUR TO CARRY OUT REAR REPAIR	700.00	<i>400</i>
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	
	TO SPRAY PAINTING ON AFFECTED AREAS	800.00	<i>500</i>
	SPRAY RUST PROOF ON AFFECTED AREA	30.00	

Date : 04/05/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ABDUL RAHMAN BIN HASBIALLAH

: AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED

Certificate No : P10298091R01

Accident Date : 26/04/2021

Vehicle No : SJN-3668-L

Make & Model : TOYOTA COROLLA ALTIS 1.6 (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO TRANSFER REAR DOOR LH FITTING	100.00	60
	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	100.00	60
	Sub Total	1765.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Remarks:

4 days - Lumpsum
Recy after repair

2,923.52

SUB TOTAL

GST 7.0 % 204.65

TOTAL 3,128.17

Surveyor's name: Rasul - 4p 90010068

Principal's name: ABDUL RAHMAN BIN HASBIALLAH

Survey Date & Time: 10/05/21 @ 1400