

Survey
7/5/2021
1457 hrs
Terim
lin

Resurvey
10/5/2021
1056 hrs
Terim
lin

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Company Reg No: 201929175W

Vehicle No:
Model and make:
Chassis No:

GBE2813H
Mercedes Benz 2007

Qty Spare Parts

- 1 Front bumper
- 1 Front bumper RH side bracket
- 1 Front bumper reinforcement
- 1 RH headlamp assy
- 1 Front apron panel
- 1 Front grille
- 1 Front grille emblem
- 1 Front RH fender
- 1 Front RH fender splash shield

List Price (\$)

\$ 886.00	1,360.90	BR ✓
\$	✓ 93.80	BR ✓
\$	✓ 837.52	BT ✓
\$ 680.00	894.00	BR ✓
\$	✓ 448.62	BR ✓
\$ 390.00	580.39	DIS ✓
\$ 68.00	128.01	NEC ✓
\$	✓ 429.17	BR ✓
\$	153.48	NDX

\$ 3,233.11	3,564.99
-10% \$ 3,233.31	356.50
\$ 3,419.80	3,208.49

Qty Spare Parts

- 1set Front bumper clips
- 1set Front apron panel clips
- 1 Front RH fender sticker

Special Nett (\$)

\$ 30.00	60.00	NEC ✓
\$	60.00	NNX
\$ 90.00	180.00	NEC ✓

(To provide invoice)

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 400.00 700.00 ✓

Spray painting on affected panels

\$ 450.00 800.00 ✓

Check wiring and lighting system

\$ 70.00 NNX

Apply rust coating on affected areas

\$ 50.00 NNX

Lump sum repair
Repair days 5

Total:

\$ 5,128.49

L/S 3,550/2

Terim
lin
14/5/2021

@ 2090
4,419.80
883.96
3535.84