



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21005571/Kuf3e2	
			Date: 05/07/2021	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHB 469B	Veh. Inspected	SMG 2184Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/05/21/2003	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	06/05/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA SIENTA G (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	MHFZ28H3900060331	Colour	METALLIC SILVER
	Odometer	157501 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	KAPSEN	6 mm
	L/H Front Tyre	185/60 R15	KAPSEN	6 mm
	R/H Rear Tyre	185/60 R15	APLUS	9 mm
	L/H Rear Tyre	185/60 R15	APLUS	9 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	02/05/2021	Inspection Date	07/05/2021
	Survey held at	HENG YAP SENG AUTO SERVICE BLK 13 SIN MENG IND. EST. SECTION B, #01-39 SINGAPORE 575657		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	