



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01

CITY HOUSE SINGAPORE 068877

ATTN.:

FAX:

NAME: Ms Leong Nyet Ken

ADDRESS: 1 Leong Piasang Batu

Singapore 197929

TEL: 97324863

WIP: 33548

EXCESS:

DATE: 29-Apr-21

VEH NO:	SKC1866R	DATE IN:		CONTACT PERSON:	Jess 8128 9802
CHASSIS NO:	JM6DK2W7AK0416088	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	CX3	DATE REG:	14-Aug-19	POLICY NO.:	

NATURE OF WORKS

Parts Description

NO	PART NO.	QTY	1st	2nd	REVISED	PRICES
1	MASCOT, REAR <i>ne /</i>	MD11B-51-730	1		-	54.30
2	ORNAMENT <i>ne /</i>	MD10J-51-771A	1		-	56.60
3	ORNAMENT, CAR NAME-REAR <i>ne /</i>	MD10J-51-721	1		-	55.70
4	REAR BUMPER <i>he /</i>	MDHYF-50-22XABB	1		-	1,088.40
5	PIN, LOCATOR <i>ne /</i>	MD10J-50-1K5	1		-	3.90
6	BRACKET, REAR @ 26.10-NECESSARY <i>? X nn</i>	MD10J-50-271	2		-	52.20
7	FASTENER @ 3.00-NECESSARY <i>ne /</i>	MB45A-56-146A	10		-	30.00
8	GROMMET @ 2.70-NECESSARY <i>ne /</i>	MBHN1-50-0Z1A	6		-	16.20
9	PAD @ 7.60-NECESSARY <i>ne /</i>	MBR55-56-994	2		-	15.20
10	REINF., REAR <i>? X SVC</i>	MDB2P-50-260A	1		-	362.80
11	RETAINER LH, REAR <i>X SVC</i>	MD10J-50-2J1B	1		-	24.60
12	RETAINER RH, REAR <i>X SVC</i>	MD10J-50-2H1B	1		-	24.60
13	TAPE @ 3.50-NECESSARY <i>ne /</i>	MG043-62-864A	2		-	7.00
14	COVER, UNDER <i>X SVC</i>	MD10J-50-C51	1		-	42.60
15	GUARD <i>? X SVC</i>	MD10J-50-371	1		-	17.10
16	CLIPS @ 2.90-NECESSARY <i>ne /</i>	MBGV4-56-145	6		-	17.40
17	PAD @ 7.80-NECESSARY <i>ne /</i>	MG001-67-061	12		-	15.60
18	SENSOR, ULTRASONIC - CENTER @ 200.50 <i>? V nw</i>	MGMC8-67-UC1	1	1pc	-	401.00
19	CORD, SHORT ULTRASONIC <i>? X SVC</i>	MD24H-67-SH0	1		-	119.70
TOTAL PARTS						2,404.90
TOTAL PARTS COST						2,404.90

Labour Description

1	MZ-BR-REAR02	REPLACE REAR BUMPER. REPAIR TAILGATE AND AREAS AFFECTED BY THE ACCIDENT.	660 -	1,320.00
---	--------------	--	-------	----------

	MZ-SP-SREAR2	SPRAY REAR BUMPER, TAILGATE.	1260	1,575.00
3	MZ-BR-REVSSEN	TO TRANSFER REVERSE SENSORS.	NETT	330.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	NETT	X 330.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NETT	150.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	180.00
7	MZ-BR-SUNDRI	SUNDRIES.	-	10 100.00

TOTAL LABOUR		3,985.00
TOTAL PARTS		2,404.90
TOTAL		6,389.90
LESS EXCESS		-
TOTAL AFTER EXCESS		6,389.90
GST 7%		447.29
GRAND TOTAL		6,837.19

SUPPLEMENTARY PARTS

NO	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	0	0				-
2	0	0				-
TOTAL PARTS						-
TOTAL PARTS COST						-

SUPPLEMENTARY LABOUR DESCRIPTION

1	#N/A					-
2	#N/A					-
SUPPLEMENT LABOUR						-
SUPPLEMENT PARTS						-
TOTAL SUPPLEMENT						-
GST 7%						-
GRAND TOTAL						-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT TAKE NOTE THAT SHOULD YOU DECIDE

TRANS EUROKARS PTE LTD

BEFORE THE REPAIRS ARE BEING CARRIED OUT, TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

Paul

Hp 90010068

4 days

11/05/21 @ 1415

Resy before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUPPLEMENTARY PARTS

<u>NO</u>		<u>PARTS NO</u>	<u>QTY</u>	<u>/UNIT</u>	<u>DISC</u>	<u>1st</u>	<u>Supp</u>	<u>REVISED</u>	<u>PRICES</u>
1	GASKET RH,LAMP-TRUNK LID nec ✍	MDB3D-51-3H8	1	41.30	✓			41.30	41.30
2	GASKET LH,LAMP-TRUNK LID nec ✍	MDB3D-51-3J8	1	41.30	✓			41.30	41.30
	TOTAL PARTS							82.60	82.60
								-	-
	TOTAL PARTS COST							82.60	82.60