

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS/AIG21005585/EVF3Q2  
**Date:** 18/06/2021

**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100326836   |
| <b>Claimant Vehicle No :</b> | SBS6610B                             | <b>Insured Vehicle No :</b> | QSR888K      |
| Date of Loss:                | 04/05/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 5286435487SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SBS6610B</b>                   |             |                   |
| Make & Model:               | MERCEDES-BENZ 200, 2.0 (A)        | Engine No:  | 902926C0991519    |
| Reg. Date:                  | 03/01/2013 (Man. Year: 2012)      | Chassis No: | WEB62808323124581 |
| Colour:                     | Multi-colour                      | Odometer:   | 581005 km         |
| Engine Capacity:            | 7700 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 275/70R22.5      | Rear Tyre Size:  | 275/70R22.5      |
| Front Left Side:  | Bridgestone 4 mm | Rear Left Side:  | Bridgestone 4 mm |
| Front Right Side: | Bridgestone 4 mm | Rear Right Side: | Bridgestone 4 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                    | 869.00            | 864.00            | 5.00              | 0.58          |
| Miscellaneous Items      | 0.00              | 0.00              | 0.00              |               |
| Labour                   | 384.00            | 384.00            | 0.00              | 0.00          |
| Paintwork Labour         | 0.00              | 0.00              | 0.00              |               |
| Towing                   | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (S\$)</b> | <b>1,253.00</b>   | <b>1,248.00</b>   | <b>5.00</b>       | <b>0.40</b>   |

**INSPECTION**

6/18/2021

Adjuster Report

Date of Assignment: 07/05/2021

Date Inspected: 07/05/2021

Estimated Period of Repair: 1.0 days

Inspected At:

SBS Transit Ltd (Bukit Batok)  
550 Bukit Batok Street 23  
Singapore 659519

---

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

6/18/2021

Adjuster Report

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Recommended Parts

| No.               | Qty | Part No. | Particulars                            | Condition     | Repairer's               | Amount        |
|-------------------|-----|----------|----------------------------------------|---------------|--------------------------|---------------|
| 1                 | 1   |          | *FACE BAR,REAR BUMPER.W/RR FOGLAMP.O/S | Broken        | 364.00 F                 | *364.00 F     |
| 2                 | 1   |          | *EXTERIOR LAMP,RR FOGLAMP              | Broken        | 29.00 F                  | *29.00 F      |
| 3                 | 1   |          | *SIGNAL LED LIGHT;AMBER                | Broken        | 36.00 F                  | *36.00 F      |
| 4                 | 1   |          | *TAIL LAMP ASSY;RIGHT,RR               | Broken        | 433.00 F                 | *433.00 F     |
| 5                 | 1   |          | *REENAIL<br>(4 Pcs)                    | Not Necessary | 5.00 F                   | *- F          |
| 6                 | 1   |          | *REENAIL<br>(2 Pcs)                    | Necessary     | 2.00 F                   | *2.00 F       |
| F=Franchise part. |     |          |                                        |               |                          |               |
|                   |     |          |                                        |               | <b>Total Parts (S\$)</b> | <b>869.00</b> |
|                   |     |          |                                        |               |                          | <b>864.00</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars                | Lab.Type | Repairer's    | Amount        |
|-------------------------------|----------------------------|----------|---------------|---------------|
| <u>Labour Items</u>           |                            |          |               |               |
| 1                             | CONTRACTORS REPAIR CHARGES | New      | 384.00        | 384.00        |
| <b>Gross Labour Cost (\$)</b> |                            |          | <b>384.00</b> | <b>384.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >