Certification for Bus Repairs

SBS Transit

CBR REF NO. : BB20211962

Depot: BB Report No.: W19972021 BUS VEHICLE NO.: SBS6610B

Driver's Co no. & Name : 82087 Haswandi Bin Hasmoon

Accident Date : 04/05/2021

Date in : 05/05/2021 **Date Out :** 07/05/2021

Yr Of Reg	Make / Model	Chassis No.
2013	MB Citaro O530, SD, AC, 2 Axle	WEB62808323124581

Stock Code	Description	Quantity		Material st(S\$)
30600745	FACE BAR.REAR BUMPER.W/RR FOGLAMP.O/S	1		\$364.00
30600031	EXTERIOR LAMP;RR FOGLAMP	1		\$29.00
30600021	SIGNAL LED LIGHT; AMBER BR	1		\$36.00
30600030	TAIL LAMP ASSY; RIGHT; RR R	1		\$433.00
30600105	TREENAIL Nec	4		\$5.00
30600105	TREENAIL	-4		(\$5.00)
30600105	TREENAIL nec	2		\$2.00
	TOTAL FOR F	PARTS	S\$	864.00
S/N	Labour / Spray Painting / Contractor Cost		An	nount
1			S\$	384.00
2 Con	ractor's repair charges		S\$	-
	TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR	COST	S\$	384.00
·	Repair cost of Advertisement / Livery		S\$	-
	TOTAL DA	MAGE	S\$	1248.00

Certification for Bus Repairs

SBS Transit

CBR REF NO.: <u>BB20211962</u>

Depot: BB Report No.: W19972021 BUS VEHICLE NO.: SBS6610B

Driver's Co no. & Name: 82087 Haswandi Bin Hasmoon

Accident Date : 04/05/2021

Yr Of Reg	Mak	e / Model	Chassis No.		
2013	MB Citaro O5	30, SD, AC, 2 Axle	WEB62808323124581		
			TOTAL DAMAGE	S\$	1248.00
			Overheads	S\$	374.40
			Towing Charges	S\$	_
Repair Period	: 1 day(s)		Loss of Use	S\$	356.29
			TOTAL LOSS	S\$	1978.69

Prepared By: Choo Wee Huat Date: 18/05/2021

Approved By

Workshop Mgr: Sim Chee Heng

Date: 21/05/2021

Survey Fee	refer to Group	Claims
TOTAL DUE	S\$	1978.69

Acknowledged By

Depot Safety: Mary Sim Kwang Boey

 $\ensuremath{^{*}}$ This is computer generated document and does not require signature

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- · Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Date: 24/05/2021

steve CLKK) 7/5/21
W/P
P/P
Resurvey Before Spray