

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 11 May 2021

Preliminary Advice

Insured Vehicle No	: SME7720D		
TP Vehicle No	: FBQ8301R	Accident Date	: 01/05/2021
Make	: PIAGGIO VESPA SPRINT 150	Assignment Date	: 07/05/2021
Date of Inspection	: 07/05/2021	Est. Duration of Repair	: 6
Inspection At	: ERZAT LEE MOTOR TRADING PTE LTD (HQ) SYNERGY@KB 25 ,, KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,360.00
Revised Amount	:S\$	7,080.00
Check Items (Estimated)	:S\$	1,400.00
Total	:S\$	8,480.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :