LKK Auto Cons Tarts hence notify RVIALUTOMOTIVE SERVICES PTE LTD • To display damaged part(s) during resuge CHANGI SOUTH AVENUE 2 #01-02 Parts prices are subject to confirmation SINGAPORE 486443 Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed: 65446676 / 65446689 FAX: 62141511 • Supplementary item(s) @@prescreened 07743D GST REG:200707743D is subject to final approval from Insurance Company 17-May-21 Acknowledged by Repairer Signature: ESTIMATE REPAIR BILL FOR HYUNDAI ION Q REGN NO: SHD 1705 C 1 pc Rear bumper 459.40 N 1 pc Rear bumper reinforcement 294.80 2 pcs Rear bumper reinforcement n/s & o/s lower bracket @ \$10.00 30.00 1 pc Rear bumper reinforcement centre lower bracket 😾 15.00 2 pcs Rear bumper n/s & o/s stay @ \$138.10 276.20 2 pcs Rear bumper n/s & o/s side bracket @ \$33.10 66.20 Rear bumper lower moulding centre 1 pc 216.50 🗸 1 pc Rear bumper lip X 47.50 SMN 1 pc Rear bumper cap hook X 9.10 1 pc Rear bumper n/s & o/s reflector @ \$31.90 63.80 \$ 1,478.50 970.7 **Less 20%** 295.70 1,182.80 776.56 S/N 1 set Rear bumper clips \$ 48.00 🗸 1 set Reverse sensor \$ 280.00 Rear number plate with casing 1 pc \$ 50.00 🗸 1 pc Rear bumper top protector \$ 80.00 🗸 178 Sundry \$ 50.00 To check wiring \$ 50.00 To dismantle / replace reverse sensor to new bumper and reset to the same 120.00 To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00 To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc \$ 650.00 Zac To putty and spray painting on rear bumper, end panel, rear bumper lower cover (Black) \$ 600.00 2 To apply rustproofing on the repaired and replaced panels. \$ 80.00 \$ 3,370.80 (ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE

ANY UNFORESEEN DAMAGES.

1354.56