

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 31797

Your Reference : Z21VC05007141
Accident Date : 30-Apr-2021

Date : 07-May-2021

Our Ref : 021181 / QUEK

PAGE : 1

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
Singapore 199555

NOT Notarised
21 May 2021
Penny Ate Paim

Foley

ESTIMATED COST OF REPAIR FOR HINO XZU710R (4009cc)(2016) YP1262Z

1 pc front bumper		Ry 580.00 c ✓
2 pcs front bumper bracket (LH/RH)	@ S\$200.00	Ry 400.00 c ✓
2 pcs front bumper fog lamp(LH/RH)	@ S\$250.00	nl/Ry 500.00 c ✓
1 pc front grille		nl/Ry 510.00 c ✓
1 pc front grille logo		nl 70.00 c ✓
10 pcs front grille clips +VE	@ S\$ 1.50	nl 15.00 c ✓
10 pcs front grille clips -VE	@ S\$ 1.50	nl 15.00 c ✓
2 pcs headlamp assy (LH/RH)	nl/Ry cm @ S\$580.00	1,160.00 c nl/Ry ✓
1 pc front panel - outer		Ry 300.00 c ✓
1 pc front panel - inner		530.00 c ?
2 pcs front panel socket cover	@ S\$ 90.00	180.00 c ?
2 pcs front wiper blade (LH/RH)	@ S\$ 65.00	nl 130.00 c ✓
2 pcs front wiper arm (LH/RH)	nl/Ry @ S\$110.00	220.00 c ✓
1 pc front wiper linkage		165.00 c ?
1 pc front wiper motor		280.00 c ?
1 pc front windscreen glass c/w moulding		cm 850.00 c ✓
1 pc air con blower		300.00 c ?
1 pc air con heater unit c/w cooling coil		1,100.00 c ?
1 pc air con heater bypass pipe (inlet)		nl 120.00 c ✓
1 pc air con heater bypass pipe (outlet)		nl 150.00 c ✓
1 pc dashboard assy		580.00 c ?
1 pc dashboard reinforcement		400.00 c ?
2 pcs brake pipe upper (LH/RH)	@ S\$145.00	290.00 c ?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : Z21VC05007141
Our Ref : 021181

Page : 2
No. : 31797

1 pc clutch pipe upper	n/s cm	160.00	c	?
2 pcs front corner panel (LH/RH)	@ S\$185.00	370.00	c	✓
1 pc n/s wingmirror - big	Br	105.00	c	—
1 pc n/s wingmirror stay cap cover	Mr	60.00	c	—
1 pc n/s wingmirror stay		210.00	c	?
1 pc n/s front door step garnish	cm	165.00	c	✓
1 pc air con liquid pipe		185.00	c	?
1 pc air con discharge pipe		240.00	c	?

10,340.00
Add 15% : 1,551.00

11,891.00

1 pc front number plate	Br	40.00	sn	20sn
1 pc front panel heat insulation		150.00	sn	?
1 pc front windscreen glass sealant	Mr	60.00	sn	✓
1 pc front windscreen glass damping seal	Mr	20.00	sn	✓
1 pc ERP bracket	Mr	26.00	sn	✓
1 pc air con condenser	Br	320.00	sn	✓
1 pc air con condenser bracket	Mr	195.00	sn	✓
1 pc air con condenser fan assy		450.00	sn	?

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

1,200.00

To remove aircon condenser, pipes
and driers. Vaccum and recharge gas

100.00

To remove and renew front wind-
screen glass and conduct water
leak test.

120.00

To remove and renew front
instrument panel assy, to rewiring
and transfer instrument fittings.

240.00

Con't Page 3 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : Z21VC05007141
Our Ref : 021181

Page : 3
No. : 31797

To putty and respray on affected
portions.

8001
1,200.00

Total : S\$16,012.00
=====

Singapore Dollars Sixteen Thousand and Twelve Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.