



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21005591/Ktf3m4 Date: 07/06/2022 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	YP 1262Z
	Policy No.	Z21VC05007141	Coverage (\$)	0.00
	Claim No.	21/21/21/VC05/024526	Excess (\$)	0.00
	Assign From	KENNY LIM	Assign Date	07/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	HINO XZU710R (M)	c.c	4009
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JHHUCS3H40K014684	Colour	WHITE
	Odometer	62178 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	700R12X10	BRIDGESTONE	8 mm
	L/H Front Tyre	700R12X10	BRIDGESTONE	8 mm
	R/H Rear Tyre	700R12X10 (D)	BRIDGESTONE	9/9 mm
	L/H Rear Tyre	700R12X10 (D)	BRIDGESTONE	9/9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/04/2021	Inspection Date	07/05/2021
	Survey held at	K.KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE, #02-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A) THE MARKET VALUE IS S\$50,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	