

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 31797

Your Reference : Z21VC05007141
Accident Date : 30-Apr-2021

Excess \$

Date : 07-May-2021

Our Ref : 021181 / QUEK

NOT Notarised

PAGE : 1

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
Singapore 199555

21 Rm @ 10,050h
Penny After Pairs

7 days

ESTIMATED COST OF REPAIR FOR HINO XZU710R (4009cc)(2016) YP1262Z

1 pc front bumper		Ry 580.00 c	✓	
2 pcs front bumper bracket (LH/RH)	@ S\$200.00	Ry 400.00 c	✓	
2 pcs front bumper fog lamp (LH/RH)	@ S\$250.00	nl/Ry 500.00 c	✓	old sum
1 pc front grille		nl/Ry 510.00 c	✓	
1 pc front grille logo		nl/Ry 70.00 c	✓	
10 pcs front grille clips +VE	@ S\$ 1.50	nl/Ry 15.00 c	✓	
10 pcs front grille clips -VE	@ S\$ 1.50	nl/Ry 15.00 c	✓	
2 pcs headlamp assy (LH/RH)	@ S\$580.00	nl/Ry 1,160.00 c	✓	old sum
1 pc front panel - outer		Ry 300.00 c	✓	
1 pc front panel - inner		Ry 530.00 c	✓	
2 pcs front panel socket cover	@ S\$ 90.00	nl/Ry 180.00 c	✓	
2 pcs front wiper blade (LH/RH)	@ S\$ 65.00	nl/Ry 130.00 c	✓	
2 pcs front wiper arm (LH/RH)	@ S\$110.00	nl/Ry 220.00 c	✓	old sum
1 pc front wiper linkage		nl/Ry 165.00 c	✓	
1 pc front wiper motor		nl/Ry 280.00 c	✓	
1 pc front windscreen glass c/w moulding		nl/Ry 850.00 c	✓	
1 pc air con blower		nl/Ry 300.00 c	✓	
1 pc air con heater unit c/w cooling coil		nl/Ry 1,100.00 c	✓	
1 pc air con heater bypass pipe (inlet)		nl/Ry 120.00 c	✓	
1 pc air con heater bypass pipe (outlet)		nl/Ry 150.00 c	✓	
1 pc dashboard assy		nl/Ry 580.00 c	✓	
1 pc dashboard reinforcement		nl/Ry 400.00 c	✓	
2 pcs brake pipe upper (LH/RH)	@ S\$145.00	nl/Ry 290.00 c	✓	

Con't Page 2 ...



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : Z21VC05007141
Our Ref : 021181

Page : 2
No. : 31797

- 1 pc clutch pipe upper
- 2 pcs front corner panel (LH/RH) @ S\$185.00
- 1 pc n/s wingmirror - big
- 1 pc n/s wingmirror stay cap cover
- 1 pc n/s wingmirror stay
- 1 pc n/s front door step garnish
- 1 pc air con liquid pipe
- 1 pc air con discharge pipe

net 160.00 c
dis 370.00 c
Bn 105.00 c
n/s 60.00 c
R 210.00 c
CM 165.00 c
Sn 185.00 c
h 240.00 c

10,340.00
Add 15% : 1,551.00

11,891.00

- 1 pc front number plate
- 1 pc front panel heat insulation
- 1 pc front windscreen glass sealant
- 1 pc front windscreen glass damping seal
- 1 pc ERP bracket
- 1 pc air con condenser
- 1 pc air con condenser bracket
- 1 pc air con condenser fan assy

20sn
Bn 40.00 sn
dis 150.00 sn
n/s 60.00 sn
R 20.00 sn
CM 26.00 sn
Bn 320.00 sn
R 195.00 sn
CM 450.00 sn

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

960
1,200.00

To remove aircon condenser, pipes
and driers. Vaccum and recharge gas

100.00

To remove and renew front wind-
screen glass and conduct water
leak test.

120.00

To remove and renew front
instrument panel assy, to rewiring
and transfer instrument fittings.

240.00

Con't Page 3 ...



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinh.com.sg

Your Reference : Z21VC05007141
Our Ref : 021181

Page : 3
No. : 31797

To putty and respray on affected
portions.

Pool
1,200.00

Total : S\$16,012.00

Singapore Dollars Sixteen Thousand and Twelve Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

$$\begin{array}{r} \$ 8315.00 \text{ Part} \\ + 157. \\ \hline \$ 9562.25 \\ \$ 876.00 \text{ s/n} \\ + \$ 2160.00 \text{ Ldn} \\ \hline \$ 12,598.25 \\ - 207. \\ \hline \$ 10,078.60 \end{array}$$

$$\begin{array}{r} 10,050/1 \\ 45 = \$ 10,100.00 \end{array}$$