

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
 Email:kentsengcarservices@gmail.com

M/s China Taiping Insurance (S) Pte Ltd DATE 10.05.2021
 3 Anson Road #16-00 Spring leaf Tower CAR NO SLE 4323 Z
 Singapore 079909 MAKE Honda Vezel

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : SLG9517 M

Pc	Pcs	RU11110488	UNIT PRICE	AMOUNT	
1	pc	Tailgate	1100	\$1,620.00	bt ✓
1	pc	Tailgate inner lock	180	\$245.00	bt ✓
1	pc	Tailgate lock catch		\$38.00	x
1	pc	Tailgate glass moulding		\$195.00	nei ✓
1	pc	Tailgate "Honda" logo		\$57.80	nei ✓
1	pc	Tailgate emblem "Vezel"		\$79.20	nei ✓
1	pc	Tailgate weatherstrip		\$195.00	at ✓
1	pc	Tail gate interior trim board	298	\$565.00	de ✓
2	pcs	Tailgate hing (left & right)	\$69.20	\$138.40	x
1	pc	Tailgate wiper motor		\$295.00	x
2	pcs	Taigate reflector (left & right)	\$360.00	\$720.00	x
1	pc	Tailgate inner compartment side trim (left)		\$335.00	x
1	pc	Tailgate inner compartment side trim (right)		\$335.00	x
1	pc	Tailgate inner floor panel (center)		\$675.60	x
2	pcs	Tailgate inner floor panel (left & right)	\$205.00	\$410.00	x
1	pc	Tailgate inner floor panel cover		\$462.00	x
1	pc	Tools & storage box		\$381.00	x
1	set	Rear number plate with casing		\$60.00	x
1	pc	Rear compartment keyless remote antenna		\$220.00	x
1	pc	Rear bumper	562.20	\$1,182.00	de ✓
2	pcs	Rear bumper side corner panel garnish	\$310.50	\$621.00	Rx ✓
2	pcs	Rear bumper reflector	\$168.00	\$336.00	UH ✓
2	pcs	Rear bumper side retainer	\$72.00	\$144.00	UH ✓
2	pcs	Rear bumper side bracket	\$116.00	\$232.00	x nm ✓
10	pcs	Rear bumper clips	\$5.00	\$50.00	3aw ✓
1	set	Rear bumper reverse sensor	SN 200	\$320.00	nm ✓
1	pc	Rear bumper under cover		\$296.00	de ✓
10	pcs	Rear bumper under cover clips	\$3.90	\$39.00	nei ✓
1	pc	Rear number plate with casing		\$70.00	x nm ✓
1	pc	Rear end panel		\$820.90	Ry ✓
1	pc	Rear end panel top garnish		\$184.00	de ✓
		1H feilump out ✓	\$462.60		

KENT SENG CAR SERVICES.

Page 1 of 2 Total

3850.80
 2% 3080.64
 SN 269

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
 Email:kentsengcarservices@gmail.com

M/s China Taiping Insurance (S) Pte Ltd DATE 10.05.2021
3 Anson Road #16-00 Spring leaf Tower CAR NO SLE 4323 Z
Singapore 079909 MAKE Honda Vezel

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : SLG9517 M

Pc	Pcs	RU11110488	UNIT PRICE	AMOUNT
		Continue from page one.		\$11,321.90
		Labour for knocking, straighten, realigning rear left & right side fender, cutting rear spare tyre tank panel, cutting rear end panel, dismantle and replace the above mentioned parts.	700	\$2,000.00
		Labour to respray rear tailgate cover (inner & outer) portion, rear end panel, rear bumper, rear spare tyre tank panel and rear bumper two side corner panel garnish.	700	\$1,800.00
		Rust-proofing on the rear accident affected.	30	\$120.00
		To testing, checking, dismantle and replace rear reverse sensor.	30	\$80.00
		To apply silicon onto rear wind screen.	60	\$80.00
		Labour to dismantle & refix rear wind screen.	120	\$180.00
		To conduct water leakage test and check electrical wiring for proper functions.	30	\$150.00
		Tan J'kh 97495749 WP' 10/5/21 e Nam - tauhin e lkhantown. 4/5 Pusing after repair 5 days	3080 3080.64 269 1670 5049.64 - LS of 4000, 5 days.	1670.

[Handwritten signature]

KENT SENG CAR SERVICES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to final information
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Page 2 of 2

\$15,731.90