

ASS. FILE BY: Tanjari

REF: Q/CTL 2005596 / T. 183.

ASSIGNMENT

21 Jul 2016

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLE 43237 Yr Regn: _____
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Vezel C.C. 1496
 Colour: Marron A/C: Insured / Std / NI / NA
 Sp. Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU11110488
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: 215/60R16

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal. 6 mm L/Bal. 6 mm
 L/Bal. 6 mm R/Bal. 6 mm
 D.O.A. _____ D.O.I. 10/5/21
 Survey held at Kent Seng
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>w/s will pass G1A.</u>
	<u>confirm LS COR:\$4000 at 5 working days</u> <u>(red:11731.9;74%)</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) Date/Time, File Return to? _____
 2) _____
 Days Of Repair: 5
 Resurvey No. of Trip: _____
 Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Insp (\$ _____)
 Misc. Fee (\$ _____)
 Survey Fee: _____
 Transportation: _____
 S + P.S. \$ _____
 Photos _____
 Other _____
 TOTAL _____

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
 Email: kentsengcarservices@gmail.com

<u>M/s China Taiping Insurance (S) Pte Ltd</u>	<u>DATE</u>	<u>10.05.2021</u>
<u>3 Anson Road #16-00 Spring leaf Tower</u>	<u>CAR NO</u>	<u>SLE 4323 Z</u>
<u>Singapore 079909</u>	<u>MAKE</u>	<u>Honda Vezel</u>

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : SLG9517 M

Pc	Pcs	RU11110488	UNIT PRICE	AMOUNT	
1	pc	Tailgate		\$1,620.00	bt/
1	pc	Tailgate inner lock		\$245.00	bt/
1	pc	Tailgate lock catch		\$38.00	x
1	pc	Tailgate glass moulding		\$195.00	na/
1	pc	Tailgate "Honda" logo		\$57.80	na/
1	pc	Tailgate emblem "Vezel"		\$79.20	na/
1	pc	Tailgate weatherstrip		\$195.00	act/
1	pc	Tail gate interior trim board		\$565.00	de/
2	pcs	Tailgate hing (left & right)	\$69.20	\$138.40	x
1	pc	Tailgate wiper motor		\$295.00	x
2	pcs	Taigate reflector (left & right)	\$360.00	\$720.00	RH x
1	pc	Tailgate inner compartment side trim (left)		\$335.00	x
1	pc	Tailgate inner compartment side trim (right)		\$335.00	x
1	pc	Tailgate inner floor panel (center)		\$675.60	x
2	pcs	Tailgate inner floor panel (left & right)	\$205.00	\$410.00	x
1	pc	Tailgate inner floor panel cover		\$462.00	x
1	pc	Tools & storage box		\$381.00	x
1	set	Rear number plate with casing		\$60.00	x
1	pc	Rear compartment keyless remote antenna		\$220.00	x
1	pc	Rear bumper		\$1,182.00	de/
2	pcs	Rear bumper side corner panel garnish	\$310.50	\$621.00	R/
2	pcs	Rear bumper reflector	\$168.00	\$336.00	RHX LH/
2	pcs	Rear bumper side retainer	\$72.00	\$144.00	RH LH na/
2	pcs	Rear bumper side bracket	\$116.00	\$232.00	x
10	pcs	Rear bumper clips	\$5.00	\$50.00	30na/
1	set	Rear bumper reverse sensor		\$320.00	200 na/
1	pc	Rear bumper under cover		\$296.00	de/
10	pcs	Rear bumper under cover clips	\$3.90	\$39.00	na/
1	pc	Rear number plate with casing		\$70.00	x
1	pc	Rear end panel		\$820.90	R/
1	pc	Rear end panel top garnish		\$184.00	de/

1M tailgate out ✓

[Signature]

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
 Email:kentsengcarservices@gmail.com

M/s China Taiping Insurance (S) Pte Ltd DATE 10.05.2021
3 Anson Road #16-00 Spring leaf Tower CAR NO SLE 4323 Z
Singapore 079909 MAKE Honda Vezel

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : SLG9517 M

Pc	Pcs	RU11110488	UNIT PRICE	AMOUNT
		Continue from page one.		\$11,321.90
		Labour for knocking, straighten, realigning rear left & right side fender, cutting rear spare tyre tank panel, cutting rear end panel, dismantle and replace the above mentioned parts.	700	\$2,000.00
		Labour to respray rear tailgate cover (inner & outer) portion, rear end panel, rear bumper, rear spare tyre tank panel and rear bumper two side corner panel garnish.	700	\$1,800.00
		Rust-proofing on the rear accident affected.	30	\$120.00
		To testing, checking, dismantle and replace rear reverse sensor.	30	\$80.00
		To apply silicon onto rear wind screen.	60	\$80.00
		Labour to dismantle & refix rear wind screen.	120	\$180.00
		To conduct water leakage test and check electrical wiring for proper functions.	30	\$150.00

Tan J'lin 97495749
 WP' 10/5/21 e lam -
 taupin @ kuantan.
 4/5 Remy after repair
 Sedy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to information
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total amount \$15,731.90

Acknowledged by Repairer
 Signature:
 Date:

KENT SENG CAR SERVICES.