

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

7-May-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6641 A

1 pc	Front n/s head lamp	\$	1,028.00 <i>Run</i>
1 pc	Bonnet grille	\$	385.00 <i>an</i>
1 pc	Front bumper	\$	531.00 <i>an</i>
1 pc	Front bumper emblem	\$	44.00 <i>x an</i>
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	16 \$	32.00 <i>ns an</i>
1 pc	Front bumper n/s upper bracket	\$	16.00 <i>X</i>
1 pc	Front bumper n/s support bracket	\$	16.00 <i>X</i>
1 pc	Front bumper n/s protector	\$	51.00 <i>X</i>
1 pc	Front bumper n/s fog lamp cover	\$	66.00 <i>X</i>
1 pc	Front bumper centre grille	\$	174.00 <i>X</i>
1 pc	Front bumper lower stiffer	\$	134.00 <i>r</i>
1 pc	Front bumper lip	\$	52.00 <i>x mis</i>
1 pc	Front n/s fender	\$	384.00 <i>bt</i>
1 pc	Front n/s fender inner shield	\$	120.00 <i>an</i>
1 pcs	Front n/s wheel cover	\$	116.00 <i>de</i>
1 pc	Front n/s rim	\$	246.00 <i>Ry</i>
1 pc	Front n/s lower arm	\$	439.00 <i>X</i>
1 pc	Front n/s shock absorber	\$	330.00 <i>X</i>
1 pc	Front n/s ball joint	\$	59.00 <i>x</i>
1 pc	Front n/s knuckle arm	\$	547.00 <i>X</i>
1 pc	Front n/s knuckle bearing	\$	157.00 <i>X</i>
1 pc	Front n/s stabilizer link	\$	86.00 <i>x</i>
		\$	5,013.00
		Less 10%	\$ 501.30
			\$ 4,511.70
			2194
			10% - 1974.60

Supp
n/s mirror assy *an* \$590

S/NETT

1 pc	Front bumper clips	\$	48.00 <i>Soner</i>
1 pc	Front n/s fender sticker	\$	30.00 <i>an</i>
1 set	Front n/s fender inner shield clips	\$	28.00 <i>2000</i>

go.

7-May-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6641 A

Sundry

\$ 50.00 x n n

To check front n/s wheel alignment

\$ 80.00 ✓

To dismantle / refit front n/s undercarriage

\$ 250.00 x n n photo -

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ 180.00 x n n

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc

\$ 800.00 400

To putty and spray painting on front bumper, front n/s fender, bonnet grille

\$ 600.00 ✓

To apply rustproofing on the repaired and replaced panels.

\$ 150.00 30

\$ 6,727.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

1110

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

3164.60

1/5 \$ 2500

04 days

Taufhi 97491749
'wp' 715771 & 1500
3-4 days

1/5 Resurvey after repair
Taufhi C. Chandra. Wm.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: