

3A Automobile Pte Ltd

No 120 Lower Delta Road #02-15 Cendex Centre Singapore 169208 Tel: 6223 1122 Fax: 6738 6666

Estimate Report

Date: 19-Oct-2017

Policy Number: 999995236/100754333-00000

Vehicles Number: SKD1838 S

Make and Model: Toyota Corolla Altis 1.6 Auto

Date Of Accident: 19-Oct-2017

AMERICAN INTERNATIONAL GROUP

78 Amoy Street

Singapore 069897

Attn: Motor Claim Department

(Claim Officer)

Tel: 64191000

Fax: 68357416

Unit	List Items	Units Price	Prices
1 pc	Rear Boot	\$290.00	\$290.00
2 pc	Rear Boot Hinges	\$15.00	\$30.00
1 pc	Rear Weatherstrip	\$45.00	\$45.00
1 pc	Rear Boot Top Lock	\$40.00	\$40.00
1 pc	Rear Boot Bottom Lock	\$10.00	\$10.00
1 pc	Rear Boot Toyota Logo	\$25.00	\$25.00
pc	Rear Boot Wording	\$20.00	\$20.00
1 pc	Rear Bumper	\$175.00	\$175.00
3 pc	Rear Bumper Side Retainer L/R	\$25.00	\$50.00
8 pc	Rear Bumper Clips	\$1.50	\$12.00
2 pc	Rear Bumper Reflector L/R	\$18.00	\$36.00
1 pc	Rear Bumper Foam	\$50.00	\$50.00
1 pc	Rear Bumper Rear End Panel	\$180.00	\$180.00
1 pc	Rear LHS Tailamp Assy	\$110.00	\$110.00
1 pc	Rear LHS Fender Shield	\$16.00	\$16.00
8 pc	Rear LHS Fender Shield Clips	\$1.50	\$12.00
1 pc	Rear Panel Top Covering	\$75.00	\$75.00

\$1,176.00

Mark up

15%

\$176.40

1 Sct Rear Reverse Sensor

S/Total

\$200.00

\$1,552.40

Labour Charges

	To Remove & Replace the Damaged Parts as Listed Above, including Reinstallments of necessary Attachments & Fittings to Facilitate Repairs; Jack, Panel Beat & Reshape the Affected Parts & Components, Correct & Realign the Necessary Parts				\$1,200.00
	To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint on Front Right Hand Side Door, & Right Side Bottom Side Skirt with Oven Spray Booth Facilities				\$1,000.00
Total					\$3,752.40

Yours faithfully,

3A Automobile Pte Ltd

Person to contact : Dennis

Mobilephone: 97868677

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten notes and signatures on the right side of the estimate, including a large bracket grouping items 1 through 17, a signature, and the number 259.

800

800

RASUL
Hp 90010068

8 days

L/S

24/10/17 @1230

Resurvey after repair