

LKK Admin

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TOH HONG EE
1 QUEENSWAY #02-66
SINGAPORE 149053

TPAXA.
Xiao Tong

Contact : 96257565

ESTIMATE

Repair Code : CLM16802
Date in : 07/05/2021
Vehicle Num. : SLS716B
Model : CITROEN DS4 CROSSBACK 1.6 BLUEHDI S&S EAT6
Chassis/Eng# : VF7NXBHZTGY551718/10JBHX3013389

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehnd</i>	1	1150.00	✓ 1,150.00
REAR BUMPER CENTER BRACKET <i>crackd.</i>	1	210.00	✓ 210.00
REAR BUMPER CENTER BRACKET RIVET <i>new</i>	4	5.00	✓ 20.00
REAR BUMPER KEYLESS SENSOR <i>crackd</i>	1	250.00	✓ 250.00
REAR BUMPER LOWER LID WITH CHROME <i>crackd</i>	1	660.00	✓ 660.00 <i>500.</i>
REAR BUMPER REFLECTOR LAMP L/R <i>LH crackd</i>	2	190.00	<i>180</i> 380.00
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	420.00	✓ 420.00
REAR BUMPER REVERSE SENSOR <i>2 pieces DM</i>	4	210.00	<i>420</i> 840.00
REAR BUMPER REVERSE SENSOR 'O' RING <i>new</i>	4	25.00	<i>40</i> 100.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	50.00	<i>60</i> 200.00
REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>new</i>	1	290.00	X 290.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	125.00	X 250.00
REAR END PANEL <i>Dented</i>	1	990.00	✓ <u>990.00</u>
REAR END PANEL AIR VENT LH <i>Rehnd</i>	1	90.00	✓ 90.00
REAR END PANEL INNER TOP GARNISH <i>crackd</i>	1	230.00	✓ 230.00
REAR LH TAILLAMP <i>crackd.</i>	1	420.00	✓ 420.00
REAR LH TAILLAMP LOWER BRACKET <i>crackd</i>	1	130.00	✓ 130.00

70.

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TOH HONG EE
 1 QUEENSWAY #02-66
 SINGAPORE 149053

Contact : 96257565

ESTIMATE

Repair Code : CLM16802
 Date in : 07/05/2021
 Vehicle Num. : SLS716B
 Model : CITROEN DS4 CROSSBACK 1.6 BLUEHDI S&S EAT6
 Chassis/Eng# : VF7NXBHZTGY551718/10JBHX3013389

	Subtotal before discount	5060	6,630.00
Percentage discount	10%	4554	663.00
	Sub-total 1		5,967.00
REAR BUMPER CLIPS - SET	1	80.00	30.00
REAR BUMPER SIDE SPOILER L/R	2	250	200.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	50.00	20.00
	Subtotal before discount		730.00
Percentage discount	0%		0.00
	Sub-total 2		730.00
	Parts-total		6,697.00

LABOUR

To reset system after repair works	400.00	x
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	100.00	80
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	100.00	60
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800.00	60
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,000.00	80
To apply anti-rust chemical on repaired and replaced panel.	100.00	60

- LRK Auto Consultants hereby notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*** This is a computer-generated document which requires no signature.***

Labour Total 2,500.00
Parts & Labour Total 9,197.00

Tolent: 6204
 H/S: A.9K

Adrian Lij
 2/S 10/05/21.

Acknowledged by Repairer

05 Days.