

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0403/2021/HR
DATE : 7-May-21
WIP : 26397

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/5/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR KIM WOOK
ADDRESS : 991 BUKIT TIMAH ROAD
#17-07
SINGAPORE 589630
TELEPHONE : HP +65 82689527
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800035204
VEHICLE NO : **SLX 8399 D**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 13/4/2018
ENGINE NO : CHZ 418472
CHASSIS NO : WAUZZZGA1JA063102
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-May-21
PLACE OF ACCIDENT : NEAR PIE SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 8399 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 250	
3	TO REMOVE & RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR & RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 ✓	
4	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00 X	
5	TO DISMANTLE AND RENEW BOTH FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ ✓ ✓	\$ 6,400.00 2250	
6	✓ TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, BONNET, HINGES, BOTH FRONT UPPER-A PILLARS AND FRONT DOORS.	\$ 7,700.00 2200	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 17,412.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 8399 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Deland</i>	1	\$	1,828.00	✓
2	FRONT BUMPER FIXING PARTS <i>Hea</i>	1	\$	347.00	x
3	FRONT BUMPER GRILLE - CENTER ?	1	\$	197.00	?
4	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>cut</i>	2	\$	340.00	✓
5	FRONT BUMPER AIR GUIDE GRILLE END CAP - LH / RH <i>Hea</i>	2	\$	118.00	x
6	FRONT BUMPER SPOILER <i>Deland</i>	1	\$	299.00	✓
7	FRONT BUMPER CLOSING ELEMENT ?	1	\$	156.00	?
8	FRONT WHEEL SPOILER - LH / RH <i>Hea</i>	2	\$	68.00	x
9	FRONT BUMPER ADAPTER - LH <i>Hea</i>	1	\$	36.00	x
10	FRONT BUMPER ADAPTER - RH	1	\$	42.00	x
11	FRONT RADIATOR GRILLE <i>cut</i>	1	\$	1,411.00	✓
12	FRONT RADIATOR STRIKER PLATE ?	1	\$	124.00	?
13	FRONT BUMPER FOAM FILLER PIECE ?	1	\$	78.00	?
14	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$	723.00	?
15	FRONT BUMPER GUIDE SECTION - LH / RH ?	2	\$	72.00	?
16	FRONT BUMPER REINFORCEMENT COVER <i>Deland</i>	1	\$	100.00	✓
17	"CAUTION" STICKER <i>Hea</i>	1	\$	14.00	✓
18	AIR CONDITIONER STICKER	1	\$	8.00	✓
19	FRONT LOW TONE HORN - LH <i>Hea</i>	1	\$	286.00	x
20	FRONT HIGH TONE HORN - RH <i>Hea</i>	1	\$	180.00	x
SUB TOTAL SPARE PARTS		:	\$	6,427.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 8399 D

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT HORN SPRING SHACKLE - LH / RH <i>Not m</i>	2	\$ 62.00	+	
22	FRONT FENDER - LH / RH <i>Regis</i>	2	\$ 2,294.00	+	
23	FRONT FENDER ATTACHMENT PARTS	1	\$ 40.00	+	
24	FRONT FENDER LONG BRACKET - LH / RH	2	\$ 96.00	+	
25	FRONT FENDER SHORT BRACKET - LH / RH	2	\$ 32.00	+	
26	FRONT FENDER BRACKET	2	\$ 46.00	+	
27	FRONT FENDER BRACKET - LH / RH	2	\$ 32.00	+	
28	FRONT FENDER BRACE - LH / RH	2	\$ 88.00	+	
29	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 392.00	+	
30	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not m</i>	1	\$ 57.00	+	
31	FRONT BONNET <i>Dented</i>	1	\$ 2,789.00	✓	
32	FRONT BONNET ATTACHMENT PARTS <i>Not m</i>	1	\$ 165.00	+	
33	FRONT BONNET LID HINGE - LH / RH	2	\$ 124.00	+	?
34	FRONT BONNET STRIKER - LH / RH	2	\$ 220.00	+	?
35	FRONT BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Not m</i>	3	\$ 90.00	✓	
36	FRONT BONNET COVER <i>Not m</i>	2	\$ 32.00	+	
37	FRONT BONNET PLENUM COVER <i>Not m</i>	1	\$ 158.00	+	
38	FRONT BINNET LID LOCK <i>Not m</i>	2	\$ 427.00	+	
39	FRONT BINNET BOWDEN CABLE - CENTER <i>Not m</i>	1	\$ 58.00	+	
40	FRONT BONNET COVER <i>Not m</i>	1	\$ 10.00	+	
SUB TOTAL SPARE PARTS		:	\$ 7,212.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 8399 D

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	FRONT BONNET RELEASE ELEMENT	1	\$ 58.00	+	
42	FRONT BONNET BOWDEN CABLE - LH / RH	2	\$ 116.00	+	
43	FRONT BONNET RELEASE LEVER	1	\$ 14.00	+	
44	HEADLIGHT MOUNTING	2	\$ 236.00	+	
45	HEADLIGHT - LH / RH	2	\$ 9,830.00	+	4715.
46	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 284.00	+	
47	HEADLIGHT HOSE	1	\$ 182.00	+	
48	FRONT RADIATOR LOCK CARRIER	1	\$ 994.00	+	
49	A/C CONDENSER	1	\$ 551.00	+	
50	COOLANT	6	\$ 142.00	+	
51	FRONT RADIATOR COOLER	1	\$ 951.00	+	
52	FRONT RADIATOR ADDITIONAL COOLER	1	\$ 859.00	+	
53	FRONT RADIATOR AIR GUIDE - LH / RH	2	\$ 62.00	?	
54	FRONT RADIATOR OUTER SEAL - RH	1	\$ 7.00	?	
55	FRONT RADIATOR UPPER AIR GUIDE - CENTRE	1	\$ 22.00	?	
56	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 644.00	+	
57	FRONT NUMBER PLATE.	S/N	\$ 60.00	+	
58	SUNDRIES		\$ 350.00	?	
TOTAL SPARE PARTS			\$ 29,001.00		
TOTAL LABOUR CHARGES			\$ 17,412.00		
GRAND TOTAL			\$ 46,413.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *07/05/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 08 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT