

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 8399 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 280 500.	
3	TO REMOVE & RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR & RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00 ✓	
4	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 560.00 X.	
5	TO DISMANTLE AND RENEW BOTH FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT, TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ ✓	\$ 6,400.00 2250.	
6	✓ TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, BONNET, HINGES, BOTH FRONT UPPER-A PILLARS AND FRONT DOORS.	\$ 7,700.00 2100	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		\$ 17,412.00	

Car-in

11/5/21

wipe 263 97

La/chai.



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6341 1183
EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIG - Adrian

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 8399 D

			DAMAGED PARTS & PRICES		REMARKS
S/N	PARTS DESCRIPTION	QTY	S/NETT		
1	FRONT BUMPER <i>Rehnd</i>	1	S	1,828.00	✓
2	FRONT BUMPER FIXING PARTS <i>see u</i>	1	S	342.00	✗
3	FRONT BUMPER GRILLE - CENTER <i>replaced</i>	1	S	197.00	✓
4	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>cut</i>	2	S	340.00	✓
5	FRONT BUMPER AIR GUIDE GRILLE END CAP - LH / RH <i>see u</i>	2	S	118.00	✗
6	FRONT BUMPER SPOILER <i>Rehnd</i>	1	S	299.00	✓
7	FRONT BUMPER CLOSING ELEMENT <i>?</i>	1	S	156.00	?
8	FRONT WHEEL SPOILER - LH / RH <i>?</i>	2	S	68.00	✗
9	FRONT BUMPER ADAPTER - LH <i>see u</i>	1	S	36.00	✗
10	FRONT BUMPER ADAPTER - RH	1	S	42.00	+
11	FRONT RADIATOR GRILLE <i>replaced</i>	1	S	1,411.00	✓
12	FRONT RADIATOR STRIKER PLATE <i>replaced</i>	1	S	124.00	✓
13	FRONT BUMPER FOAM FILLER PIECE <i>cut/cast</i>	1	S	78.00	✓
14	FRONT BUMPER REINFORCEMENT BEAM <i>Replaced</i>	1	S	723.00	✓
15	FRONT BUMPER GUIDE SECTION - LH / RH <i>?</i>	2	S	72.00	?
16	FRONT BUMPER REINFORCEMENT COVER <i>Rehnd</i>	1	S	100.00	✓
17	"CAUTION" STICKER <i>see</i>	1	S	14.00	✓
18	AIR CONDITIONER STICKER	1	S	8.00	✓
19	FRONT LOW TONE HORN - LH <i>He also</i>	1	S	286.00	✗
20	FRONT HIGH TONE HORN - RH <i>He also</i>	1	S	180.00	✗
SUB TOTAL SPARE PARTS			:	\$ 6,427.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
*SPARE PARTS ARE SPECIAL NETT.

(8 days)

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 8399 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT HORN SPRING SHACKLE - LH / RH <i>Not in</i>	2	\$ 62.00	*
22	FRONT FENDER - LH / RH <i>Reqir</i>	2	\$ 2,294.00	*
23	FRONT FENDER ATTACHMENT PARTS	1	\$ 40.00	*
24	FRONT FENDER LONG BRACKET - LH / RH	2	\$ 96.00	*
25	FRONT FENDER SHORT BRACKET - LH / RH	2	\$ 32.00	*
26	FRONT FENDER BRACKET	2	\$ 46.00	*
27	FRONT FENDER BRACKET - LH / RH	2	\$ 32.00	*
28	FRONT FENDER BRACE - LH / RH	2	\$ 88.00	*
29	FRONT WHEEL HOUSING LINER - LH / RH <i>Not in</i>	2	\$ 392.00	*
30	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not in</i>	1	\$ 57.00	*
31	FRONT BONNET <i>Dented</i>	1	\$ 2,789.00	✓
32	FRONT BONNET ATTACHMENT PARTS <i>Not in</i>	1	\$ 165.00	*
33	FRONT BONNET LID HINGE <i>Best</i>	2	\$ 124.00	✓
34	FRONT BONNET STRIKER - LH / RH	2	\$ 223.00	?
35	FRONT BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Not in</i>	3	\$ 90.00	✓
36	FRONT BONNET COVER <i>Not in</i>	2	\$ 32.00	*
37	FRONT BONNET PLENUM COVER <i>Not in</i>	1	\$ 158.00	*
38	FRONT BINNET LID LOCK <i>Not in</i>	2	\$ 427.00	*
39	FRONT BINNET BOWDEN CABLE - CENTER <i>Not in Dented</i>	5	\$ 58.00	✓
40	FRONT BONNET COVER <i>Not in</i>	1	\$ 10.00	✓
SUB TOTAL SPARE PARTS			\$ 7,212.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6041 1103
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 8399 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT BONNET RELEASE ELEMENT	1 S	58.00	+
42	FRONT BONNET BOWDEN CABLE - LH / RH	2 S	116.00	✓
43	FRONT BONNET RELEASE LEVER	1 S	14.00	✓
44	HEADLIGHT MOUNTING - LH / RH	2 S	136.00	✓
45	HEADLIGHT - LH / RH	2 S	9,830.00	4715
46	HEADLIGHT LIFT CYLINDER - LH / RH	2 S	284.00	+
47	HEADLIGHT HOSE	1 S	182.00	✓
48	FRONT RADIATOR LOCK CARRIER	1 S	994.00	✓
49	A/C CONDENSER	1 S	551.00	✓
50	COOLANT	6 S	142.00	✓
51	FRONT RADIATOR COOLER	1 S	951.00	+
52	FRONT RADIATOR ADDITIONAL COOLER	1 S	859.00	+
53	FRONT RADIATOR AIR GUIDE - LH / RH	2 S	62.00	✓
54	FRONT RADIATOR OUTER SEAL - RH	1 S	7.00	✓
55	FRONT RADIATOR UPPER AIR GUIDE - CENTRE	1 S	22.00	✓
56	FRONT WHEEL ARCH COVER - LH / RH	2 S	644.00	✓
57	FRONT NUMBER PLATE	S/N	60.00	✓
58	SUNDRIES		350.00	?
TOTAL SPARE PARTS			\$ 29,001.00	
TOTAL LABOUR CHARGES			\$ 17,412.00	
GRAND TOTAL			\$ 46,413.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT

Adrian Lj
 14/08/21
 H.S.