

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref

Via Fax

Date

Your Insured

SGQ 6336U

Time of Fax

Date of Acc

06.05.202

Attn: Motor Claims Department

AT 6

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH_A 45437

Our client has engaged us to repair the above vehicle and submit claims against the other party/partiesinvolved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- Our initial estimate of repairs of the damaged vehicle; i)
- Accident report made by our client. ii)

I would appreciate it if you could call us to arrange for the survey of the vehicle:

Ms. Loke Wei Yieng (yy) Tel: 62148355 or HP: 86285336

♦ Jumani Bin Masudin

Tel: 6214 8315 or HP: 9635 5305 Tel: 6214 8398 or HP: 9635 8546

♦ Lim Tien Siong ♦ Chiang Liat Choon

Tel: 6214 8314 or HP: 9296 6006

lokewy@sparkcarcare.com

Fax no. 65468156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Taxi Accident Repair

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHA4543Z

DOA: 06/05/21

Date: 07/05/2021

Make

: HYUNDAI

Insurance: AIG

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
	1 FRT BUMPER COVER			\$418.30
1	FRT BUMPER CLIPS		\$2.20	\$22.00
	1 FRT BUMPER BRACKET RH		1	\$28.00
	FRT FENDER RH			\$588.80
	FRT FENDER SHIELD RH			\$164.70
	FRT FENDER EMBLEM 'BLUE DRIVE' RH			\$26.60
	FRT WHEEL HUB CAP RH			\$346.40
	SUB TOTAL			\$1,594.80
	LESS 20%			\$318.96
	DISCOUNTED TOTAL			\$1,275.84
	Labour Charge			
	PANEL BEATING			\$800.00
	SPRAY PAINTING CHARGE			\$600.00
	TUFF KOTE			\$50.00
	TOTAL LABOUR			\$1,450.00
	ESTIMATE TOTAL		_	\$2,725.84

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717

Date/Time: 07.05.2021 12:57

Page : 1

Team: ARC Repair TP(CLSO)1 JOB CARD

Sales Order: 4078184

JC NO.:305467683

ISTOMER

(P)

S/NO

JOB DESCRIPTION

REGN NO.: SHA4543Z

MILEAGE

FUEL

}/MS

COMFORT TRANSPORTATION PTE LTD

STOMER NO. 383 SIN MING DRIVE

Singapore SINGAPORE 575717

LABOR CODE

65508755 - (R)

MODEL IONIQ(G3)

E.....1/2..... 06.05.2021 21:00

returned to Service Reception upon collection

YR OF MANU. 22.10.2019

HYUNDAI

TARGET DATE


CHASSIS CODE KMHC851CVLU186599 COMPLETION DATE/TIME:

COUNT CARD NO.

Accident Date: 06.05.2021

NATURE: 3P 06.05.2021

DESCRIPTION



ECKED & PASSED OUT BY: SERVICE ADVISOR CUSTOMER'S SIGNATURE wledgement Slip Exit Pass Vehicle No.: SHA4543Z YY AIG ∍ No.: SHA4543Z of Service Advisor Signature/Date Name of Service Advisor Date

To be kept by Security Guard