## MFORT TRANSPORTATION PTE LTD

**EPAIR ESTIMATE** 

ehicle No.: SHA4543Z

DOA: 06/05/21

Make

: HYUNDAI

Date: 07/05/2021

Insurance: AIG

MVA: MS. LOKE YY

Model	: IONIQ(G3)		MVA: MS. LOKE YY	
Qty	Parts Description / Labour	Туре	Unit Price	Amount
	1 FRT BUMPER COVER 10 FRT BUMPER CLIPS 1 FRT BUMPER BRACKET RH 1 FRT FENDER RH 1 FRT FENDER SHIELD RH 1 FRT FENDER EMBLEM 'BLUE DRIVE' RH 1 FRT WHEEL HUB CAP RH		\$ <del>2.2</del> 0	Ry \$418.30 ny x \$22.00 ny x \$28.00 Ry \$588.80 ny x \$164.70 new \$26.60 cut \$346.40
	SUB TOTA  LESS 20 <sup>o</sup> DISCOUNTED TOTA	%	373	\$1,594.80 \$318.96 <b>\$1,275.84</b>
	Labour Charge PANEL BEATING SPRAY PAINTING CHARGE TUFF KOTE		1025	525 \$800.0 500 \$600.0 ***11 \$50.0
	TOTAL LABO	UR	i i	24 450
	ESTIMATE TO	TAL.	\$ 1323 08d	\$2,725

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Taupm 9779749

'WP? 3/5/21 e 1450

taufhi a Chlorison

pp Norm befor pour.

02/3days